

序号	报告编号	发布日期	结论	影像资料
113	GX-B1534/20-2-24036	2024. 9. 23	所检项目合格。	 <p>2024/03/25</p>
114	GX-B1534/20-2-24037	2024. 9. 23	所检项目合格。	 <p>2024/03/25</p>

115	GX-B1534/20-2-24038	2024. 9. 23	所检项目合格。	 <p>2024/03/25</p>
116	GX-B1534/20-2-24039	2024. 9. 23	所检项目合格。	 <p>2024/03/25</p>

117	GX-B1534/20-2-24040	2024. 9. 23	所检项目合格。	 <p>2024/03/25</p>
118	GX-B1534/20-2-24041	2024. 9. 23	所检项目合格。	 <p>2024/03/25</p>

119	GX-B1534/20-2-24042	2024. 9. 23	所检项目合格。	
120	GX-B1534/20-2-24043	2024. 9. 23	所检项目合格。	

121	GX-B1534/20-2-24044	2024. 9. 23	所检项目合格。	
122	GX-B1534/20-2-24045	2024. 9. 23	所检项目合格。	

123	GX-B1534/20-2-24046	2024. 9. 23	所检项目合格。	
124	GX-B1534/20-2-24047	2024. 9. 23	所检项目合格。	

125	GX-B1534/20-2-24048	2024. 9. 23	所检项目合格。	
126	GX-B1534/20-2-24049	2024. 9. 23	所检项目合格。	

127	GX-B1534/20-2-24050	2024. 9. 23	所检项目合格。	
128	GX-B1598/24-2-24187	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为1.66%，小于5%为正常。	


129	GX-B1598/24-2-24188	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为1.51%， 小于5%为正常。	
130	GX-B1598/24-2-24189	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为1.72%， 小于5%为正常。	

131	GX-B1598/24-2-24190	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为1.64%， 小于5%为正常。	
132	GX-B1598/24-2-24191	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为1.53%， 小于5%为正常。	

133	GX-B1598/24-2-24192	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为1.38%， 小于5%为正常。	
134	GX-B1598/24-2-24193	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为0.95%， 小于5%为正常。	

135	GX-B1598/24-2-24194	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为0.78%， 小于5%为正常。	
136	GX-B1598/24-2-24195	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为1.59%， 小于5%为正常。	

137	GX-B1598/24-2-24196	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为3.62%， 小于5%为正常。	 A photograph of a worker wearing a red hard hat, safety glasses, and a grey safety harness. The worker is positioned on a wooden structure, possibly a scaffolding or part of a machine, in an industrial setting. A date stamp '2024/9/10' is visible in the bottom right corner of the image.
138	GX-B1598/24-2-24197	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为3.48%， 小于5%为正常。	 A photograph of a worker wearing a red hard hat, safety glasses, and a grey safety harness. The worker is standing on a wooden platform or scaffolding in an industrial environment. A date stamp '2024/9/10' is visible in the bottom right corner of the image.


139	GX-B1598/24-2-24198	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为3.37%， 小于5%为正常。	
140	GX-B1598/24-2-24199	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为2.66%， 小于5%为正常。	

141	GX-B1598/24-2-24200	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为3.20%， 小于5%为正常。	
142	GX-B1598/24-2-24201	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为2.83%， 小于5%为正常。	

143	GX-B1598/24-2-24202	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为2.91%， 小于5%为正常。	
144	GX-B1598/24-2-24203	2024. 9. 23	实测钢丝绳有效截面积损失百分比最大为2.60%， 小于5%为正常。	

145	GX-B1418/23-2-24017	2024. 9. 20	综合判定：合格。			
146	GX-B1418/23-2-24018	2024. 9. 20	综合判定：合格。			

147	GX-B1418/23-2-24019	2024. 9. 20	综合判定：合格。	
148	GX-B1418/23-2-24020	2024. 9. 20	综合判定：合格。	

149	GX-B1328/20-2-24088	2024. 9. 26	所检项目合格。	
150	GX-B1328/20-2-24089	2024. 9. 26	所检项目合格。	

151	GX-B1598/24-2-24204	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 1.78%，小于5%为正常 。	
152	GX-B1598/24-2-24205	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 1.63%，小于5%为正常 。	

153	GX-B1598/24-2-24206	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 1.35%，小于5%为正常 。	 <p>2024/9/13</p>
154	GX-B1598/24-2-24207	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 1.46%，小于5%为正常 。	 <p>2024/9/13</p>

155	GX-B1310/21-2-24319	2024. 9. 20	符合标准要求。		 <p>2024/09/07</p>	
156	GX-B1310/21-2-24320	2024. 9. 20	符合标准要求。		 <p>2024/09/07</p>	

157	GX-B1515/22-2-24012	2024. 9. 26	滚筒绳衬直径与钢丝绳直径之比小于50倍。 除上述问题外，其余所检项目合格。	
158	GX-B1310/21-2-24322	2024. 9. 20	符合标准要求。	

159	GX-B1427/21-2-24322	2024. 9. 20	符合标准要求。	 <p>2024/09/10</p>
160	GX-B1428/21-2-24337	2024. 9. 25	无缺陷迹痕显示。	 <p>2024/08/06</p>

161	GX-B1428/21-2-24338	2024. 9. 25	无缺陷迹痕显示。	 A photograph showing two workers in safety gear (hard hats, reflective vests) inspecting a structure at night. One worker is kneeling and using a tool, while the other stands nearby. A bright light source is visible in the foreground. The date stamp '2024/08/07' is visible in the bottom right corner of the image.	
162	GX-B1416/22-2-24025	2024. 9. 25	综合判定：合格。	 A photograph showing a worker in safety gear (hard hat, reflective vest) inspecting a structure at night. The worker is standing on a platform or walkway, pointing towards the structure. A bright light source is visible in the foreground. The date stamp '2024/9/13' is visible in the bottom right corner of the image.	

163	GX-B1416/22-2-24026	2024. 9. 25	综合判定：合格。	
164	GX-B1310/21-2-24308	2024. 9. 25	符合标准要求。	

165	GX-B1310/21-2-24315	2024. 9. 20	符合标准要求。			
166	GX-B1310/21-2-24316	2024. 9. 20	符合标准要求。			

167	GX-B1515/22-2-24011	2024. 9. 22	所检项目合格。	
168	GX-B1598/24-2-24177	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 1.48%，小于5%为正常 。	

169	GX-B1598/24-2-24178	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 1.77%，小于5%为正常 。		
170	GX-B1598/24-2-24179	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 1.78%，小于5%为正常 。		

171	GX-B1598/24-2-24180	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 1.60%，小于5%为正常 。	
172	GX-B1598/24-2-24181	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 2.15%，小于5%为正常 。	

173	GX-B1598/24-2-24182	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 1.92%，小于5%为正常 。	 <p>2024/09/05</p>
174	GX-B1598/24-2-24183	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 2.24%，小于5%为正常 。	 <p>2024/09/05</p>

175	GX-B1598/24-2-24184	2024. 9. 25	实测钢丝绳有效截面积 损失百分比最大为 1.88%，小于5%为正常 。	
176	GX-B1534/20-2-24124	2024. 9. 26	所检项目合格。	 2024/09/12

177	GX-B1310/21-2-24336	2024. 9. 26	符合标准要求。	 <p>2024/09/12</p>
178	GX-B1404/20-2-24029	2024. 9. 25	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	 <p>2024-09-05</p>

179	GX-B1404/20-2-24030	2024. 9. 25	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
180	GX-B1404/20-2-24031	2024. 9. 25	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

181	GX-B1404/20-2-24032	2024. 9. 25	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	 <p>2024-09-06</p>
182	GX-B1310/21-2-24309	2024/9/25	符合标准要求。	 <p>2024/08/29</p>

183	GX-B1428/21-2-24309	2024/9/25	无缺陷迹痕显示。	
184	GX-B1310/21-2-24310	2024/9/25	符合标准要求。	

185	GX-B1428/21-2-24310	2024/9/25	无缺陷迹痕显示。	
186	GX-B1310/21-2-24311	2024/9/25	符合标准要求。	

187	GX-B1428/21-2-24311	2024/9/25	无缺陷迹痕显示。	 A worker wearing a red hard hat and a blue safety vest is inspecting a large, orange, spherical object in a dark environment. The worker is holding a flashlight, and the scene is dimly lit. A timestamp '2024/08/30' is visible in the bottom right corner of the image.
188	GX-B1310/21-2-24312	2024/9/25	符合标准要求。	 A worker wearing a red hard hat and a blue safety vest is standing next to a large, orange, curved structure. The worker is holding a clipboard and looking at it. The scene is brightly lit. A timestamp '2024/08/30' is visible in the bottom right corner of the image.

189	GX-B1428/21-2-24312	2024/9/25	无缺陷迹痕显示。	
190	GX-B1310/21-2-24317	2024/9/25	符合标准要求。	

191	GX-B1428/21-2-24317	2024/9/25	无缺陷迹痕显示。	
192	GX-B1310/21-2-24318	2024/9/25	符合标准要求。	

193	GX-B1428/21-2-24318	2024/9/25	无缺陷迹痕显示。	
194	GX-B1598/24-2-24208	2024. 9. 29	实测钢丝绳有效截面积损失百分比最大为1.02%，小于5%为正常。	

195	GX-B1598/24-2-24209	2024. 9. 29	实测钢丝绳有效截面积损失百分比最大为0.94%， 小于5%为正常。	
196	GX-B1301/23-2-24008	2024/9/30	综合判定:合格。	