



序号	报告编号	发布日期	结论	影像资料
20	GX-B1310/21-1-22054 替换GX-B1310/21-1-22035	2022/6/7	合格	
21	GX-B1310/21-1-22053	2022/6/7	合格	 A photograph showing a worker in a dark environment, possibly a tunnel or underground facility, performing maintenance or inspection on a ceiling structure. The worker is wearing a dark jacket and a red safety harness. The ceiling has a complex, curved design with recessed lighting. A red timestamp '2022.6.25' is visible in the bottom right corner of the image.
22	GX-B1515/20-1-22005	2022/6/7	合格	 A photograph showing a large, curved, light-colored structure, possibly a tunnel or underground facility, illuminated by a bright light source. The structure has a smooth, curved surface and is surrounded by a dark environment. A red timestamp '2022.6.25' is visible in the bottom right corner of the image.
23	GX-B1309/21-1-22010	2022/6/7	合格	 A photograph showing a worker in a red safety suit and white helmet, standing on a yellow and black safety railing. The worker is looking down at something in their hands. The background shows a tunnel or underground facility with concrete walls and pipes. A yellow timestamp '2022.6.20' is visible in the bottom left corner of the image.

24	GX-B1500/21-1-22035	2022/6/7	合格		
25	GX-B1500/21-1-22036	2022/6/7	合格		
26	GX-B1500/21-1-22037	2022/6/7	合格		

27	GX-B1309/21-1-22011	2022/6/7	合格	
28	GX-B1500/21-1-22038	2022/6/7	合格	
29	GX-B1500/21-1-22039	2022/6/7	合格	

30	GX-B1500/21-1-22040	2022/6/7	合格	
31	GX-B1382/21-1-22004	2022/6/8	合格	
32	GX-B1383/21-1-22007	2020/6/8	合格	

33	GX-B1383/21-1-22008	2020/6/8	合格	
34	GX-B1383/21-1-22009	2020/6/8	合格	
35	GX-B1383/21-1-22010	2020/6/8	合格	