






序号	报告编号	发布日期	结论	影像资料
5	GX-B1404/20-C-22017	2022/6/13	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。	
6	GX-B1404/20-C-22018	2022/6/13	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。	
7	GX-B1404/20-C-22019	2022/6/13	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。	




8	GX-B1404/20-C-22020	2022/6/13	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	
9	GX-B1404/20-C-22021	2022/6/13	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	
10	GX-B1404/20-C-22022	2022/6/13	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	

11	GX-B1404/20-C-22023	2022/6/13	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>		
12	GX-B1404/20-C-22024	2022/6/13	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>		
13	GX-B1404/20-C-22025	2022/6/13	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>		

14	GX-B1404/20-C-22026	2022/6/13	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	
15	GX-B1404/20-C-22027	2022/6/13	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	
16	GX-B1404/20-C-22028	2022/6/13	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	

17	GX-B1404/20-C-22006	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>		
18	GX-B1404/20-C-22007	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>		
19	GX-B1404/20-C-22008	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>		

20	GX-B1404/20-C-22009	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>		 <p>2022.5.8</p>	
21	GX-B1404/20-C-22010	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>		 <p>2022.5.8</p>	
22	GX-B1404/20-C-22011	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>		 <p>2022.5.8</p>	

23	GX-B1404/20-C-22012	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>			
24	GX-B1404/20-C-22013	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>			
25	GX-B1404/20-C-22014	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>			




26	GX-B1404/20-C-22015	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	
27	GX-B1404/20-C-22016	2022/6/14	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	
28	GX-B1423-20-C-22204	2022年6月14日	合格	

29	GX-B1423-20-C-22205	2022年6月14日	合格	
30	GX-B1423-20-C-22206	2022年6月14日	合格	
31	GX-B1423-20-C-22207	2022年6月14日	合格	

32	GX-B1423-20-C-22208	2022年6月14日	合格	
33	GX-B1423-20-C-22209	2022年6月14日	合格	
34	GX-B1423-20-C-22210	2022年6月14日	合格	

35	GX-B1423-20-C-22211	2022年6月14日	合格	
36	GX-B1423-20-C-22212	2022年6月14日	合格	
37	GX-B1423-20-C-22213	2022年6月14日	合格	

38	GX-B1423-20-C-22214	2022年6月14日	合格	 A yellow and grey truck with the number '200' on its side. A person in a grey uniform stands next to it. A yellow timestamp '2022/4/3' is in the bottom right corner.
39	GX-B1423-20-C-22215	2022年6月14日	合格	 A yellow and grey truck with the number '201' on its side. A person in a grey uniform stands next to it. A yellow timestamp '2022/4/3' is in the bottom right corner.
40	GX-B1423-20-C-22216	2022年6月14日	合格	 A yellow and grey truck with the number '202' on its side. A person in a grey uniform stands next to it. A yellow timestamp '2022/4/3' is in the bottom right corner.

41	GX-B1423-20-C-22217	2022年6月14日	合格	
42	GX-B1423-20-C-22218	2022年6月14日	合格	
43	GX-B1423-20-C-22219	2022年6月14日	合格	

44	GX-B1423-20-C-22220	2022年6月14日	合格	
45	GX-B1423-20-C-22221	2022年6月14日	合格	
46	GX-B1423-20-C-22222	2022年6月14日	合格	

47	GX-B1423-20-C-22223	2022年6月14日	合格	 A yellow dump truck with the number '21' painted on its side. A person in a grey uniform is standing near the front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2022/4/3' is visible in the bottom right corner of the image.
48	GX-B1423-20-C-22224	2022年6月14日	合格	 A yellow dump truck with the number '207' painted on its side. A person in a grey uniform is standing near the front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2022/4/3' is visible in the bottom right corner of the image.
49	GX-B1423-20-C-22225	2022年6月14日	合格	 A yellow dump truck with the number '150' painted on its side. A person in a grey uniform is standing near the front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2022/4/3' is visible in the bottom right corner of the image.

50	GX-B1423-20-C-22226	2022年6月14日	合格	
51	GX-B1423-20-C-22227	2022年6月14日	合格	
52	GX-B1423-20-C-22228	2022年6月14日	合格	

53	GX-B1423-20-C-22229	2022年6月14日	合格	 A yellow XCMG 133 dump truck is shown from a side-front perspective. A person in a grey uniform stands next to the front wheel. The truck has '133' and 'XCMG' written on the side. A yellow timestamp '2022/6/14' is visible in the bottom right corner of the image.
54	GX-B1423-20-C-22230	2022年6月14日	合格	 A yellow XCMG 135 dump truck is shown from a side-front perspective. A person in a grey uniform stands next to the front wheel. The truck has '135' and 'XCMG' written on the side. A yellow timestamp '2022/6/14' is visible in the bottom right corner of the image.
55	GX-B1423-20-C-22231	2022年6月14日	合格	 A yellow XCMG 136 dump truck is shown from a side-front perspective. A person in a grey uniform stands next to the front wheel. The truck has '136' and 'XCMG' written on the side. A yellow timestamp '2022/6/14' is visible in the bottom right corner of the image.

56	GX-B1423-20-C-22232	2022年6月14日	合格	
57	GX-B1423-20-C-22233	2022年6月14日	合格	
58	GX-B1423-20-C-22234	2022年6月14日	合格	

59	GX-B1423-20-C-22235	2022年6月14日	合格	
60	GX-B1423-20-C-22236	2022年6月14日	合格	
61	GX-B1423-20-C-22237	2022年6月14日	合格	

62	GX-B1423-20-C-22238	2022年6月14日	合格	
63	GX-B1423-20-C-22239	2022年6月14日	合格	
64	GX-B1423-20-C-22240	2022年6月14日	合格	




65	GX-B1423-20-C-22241	2022年6月14日	合格	
66	GX-B1423-20-C-22242	2022年6月14日	合格	
67	GX-B1423-20-C-22243	2022年6月14日	合格	

68	GX-B1423-20-C-22244	2022年6月14日	合格	
69	GX-B1423-20-C-22245	2022年6月14日	合格	
70	GX-B1423-20-C-22246	2022年6月14日	合格	

71	GX-B1423-20-C-22247	2022年6月14日	合格	
72	GX-B1423-20-C-22248	2022年6月14日	合格	
73	GX-B1423-20-C-22249	2022年6月14日	合格	

74	GX-B1423-20-C-22250	2022年6月14日	合格	
75	GX-B1423-20-C-22251	2022年6月14日	合格	
76	GX-B1423-20-C-22252	2022年6月14日	合格	

77	GX-B1423-20-C-22253	2022年6月14日	合格	
78	GX-B1423-20-C-22254	2022年6月14日	合格	
79	GX-B1423-20-C-22255	2022年6月14日	合格	

80	GX-B1423-20-C-22256	2022年6月14日	合格	
81	GX-B1423-20-C-22257	2022年6月14日	合格	
82	GX-B1423-20-C-22258	2022年6月14日	合格	

83	GX-B1423-20-C-22259	2022年6月14日	合格	
84	GX-B1423/20-C-22185	2022/6/17	合格	
85	GX-B1423/20-C-22186	2022/6/17	合格	

86	GX-B1423/20-C-22187	2022/6/17	合格	
87	GX-B1423/20-C-22188	2022/6/17	合格	
88	GX-B1423/20-C-22189	2022/6/17	合格	

89	GX-B1423/20-C-22190	2022/6/17	合格	
90	GX-B1423/20-C-22191	2022/6/17	合格	
91	GX-B1423/20-C-22192	2022/6/17	合格	

92	GX-B1423/20-C-22193	2022/6/17	合格	
93	GX-B1423/20-C-22194	2022/6/17	合格	
94	GX-B1423/20-C-22195	2022/6/17	合格	

95	GX-B1423/20-C-22196	2022/6/17	合格	
96	GX-B1423/20-C-22197	2022/6/17	合格	
97	GX-B1423/20-C-22198	2022/6/17	合格	

98	GX-B1423/20-C-22199	2022/6/17	合格	
99	GX-B1423/20-C-22200	2022/6/17	合格	
100	GX-B1423/20-C-22201	2022/6/17	合格	

101	GX-B1423/20-C-22202	2022/6/17	合格	
102	GX-B1423/20-C-22203	2022/6/17	合格	

103	GX-B1306/21-C-22001	2022/6/22	所检项目合格	
104	GX-B1306/21-C-22002	2022/6/22	所检项目合格	

105	GX-B1306/21-C-22003	2022/6/22	所检项目合格	
106	GX-B1306/21-C-22004	2022/6/22	所检项目合格	

107	GX-B1306/21-C-22005	2022/6/22	所检项目合格	 <p>A photograph of a green electrical control panel. The panel is mounted on a wall and features a digital display showing '0000', several analog gauges, and various control buttons and switches. A yellow timestamp '2022/3/26' is visible in the bottom right corner of the image.</p>
108	GX-B1306/21-C-22006	2022/6/22	所检项目合格	 <p>A photograph of a green electrical control panel, similar to the one in the first row. It has a digital display showing '0000', analog gauges, and control elements. A yellow timestamp '2022/3/26' is visible in the bottom right corner of the image.</p>

109	GX-B1306/21-C-22007	2022/6/22	所检项目合格	 A close-up photograph of a control panel for a crane. The panel is black with a silver border and features a central screen displaying a camera feed. Above the screen are several buttons labeled 'F1' through 'F6'. To the right of the screen are various controls, including a green 'START' button, a red 'STOP' button, and several smaller buttons labeled 'SCUM', '3.15A', 'SA', and '300V'. A yellow date stamp '2022/4/7' is visible in the bottom right corner of the image.
110	GX-B1424/20-C-22003	2022. 7. 1	依据NB/T 10176-2019单轨吊车 所检项目合格。	 A photograph showing several workers in a dark tunnel or underground setting. They are wearing red hard hats and bright headlamps, illuminating the scene. The workers are standing on a narrow track or platform. A yellow date stamp '2022/5/25' is visible in the bottom right corner of the image.

111	GX-B1424/20-C-22004	2022.7.1	依据NB/T 10176-2019单轨吊车所检项目合格；依据MT/T 220-1990 尾气所检项目合格。	 <p>2022/5/7</p>
112	GX-B1424/20-C-22005	2022.7.1	依据NB/T 10176-2019单轨吊车所检项目合格。	 <p>2022/6/7</p>

113	GX-B1424/20-C-22006	2022. 7. 1	依据NB/T 10176-2019单轨吊车 所检项目合格。			
114	GX-B1381/20-C-22007	2022. 7. 1	所检项目合格。			

115	GX-B1302/21-C-22001	2022. 6. 21	合格	
116	GX-B1328/20-C-22003	2022. 6. 21	本次共检绝缘手套100只，100只绝缘手套合格。	

117	GX-B1328/20-C-22004	2022. 6. 21	本次共检绝缘鞋100只，100只绝缘鞋合格。	
118	GX-B1308/21-C-22005	2022. 6. 22	所检项目合格。	

119	GX-B1308/21-C-22006	2022. 6. 22	所检项目合格。	 <p>A photograph showing two workers in a tunnel. They are wearing red hard hats and dark clothing. They are standing next to a piece of blue equipment. The tunnel walls are concrete and there are pipes and cables visible. A date stamp '2022/5/8' is visible in the bottom right corner of the photo.</p>
120	GX-B1308/21-C-22007	2022. 6. 22	所检项目合格。	 <p>A photograph showing industrial machinery in a tunnel. The machinery is blue and green. There are pipes and cables visible. The tunnel walls are concrete. A date stamp '2022/5/7' is visible in the bottom right corner of the photo.</p>

121	GX-B1308/21-C-22008	2022. 6. 22	所检项目合格。	 A photograph showing a long, narrow tunnel with industrial machinery. The machinery is primarily blue and yellow. A person in a red hard hat and dark clothing is visible in the distance. The date '2022/5/7' is printed in yellow in the bottom right corner.
122	GX-B1499/21-C-22013	2022. 6. 22	所检项目合格。	 A photograph showing two workers in red hard hats and dark clothing standing in a tunnel. They are positioned next to a large, grey industrial motor. The date '2022/5/6' is printed in yellow in the bottom right corner.

123	GX-B1499/21-C-22014	2022. 6. 22	所检项目合格。	
124	GX-B1499/21-C-22015	2022. 6. 22	所检项目合格。	


125	GX-B1499/21-C-22016	2022. 6. 22	所检项目合格。			
126	GX-B1499/21-C-22017	2022. 6. 22	所检项目合格。			

127	GX-B1499/21-C-22018	2022. 6. 22	所检项目合格。		 A photograph showing two workers in dark blue uniforms and red hard hats in a tunnel. They are standing next to a piece of blue machinery. One worker is holding a clipboard and a flashlight. The tunnel walls are concrete with some pipes and cables. A yellow and black striped safety barrier is in the foreground. A yellow timestamp '2022/5/8' is visible in the bottom right corner of the photo.
128	GX-B1499/21-C-22019	2022. 6. 22	所检项目合格。		 A photograph showing two workers in dark blue uniforms and red hard hats in a tunnel. They are standing next to a piece of blue machinery. One worker is holding a clipboard and a flashlight. The tunnel walls are concrete with some pipes and cables. A yellow and black striped safety barrier is in the foreground. A yellow timestamp '2022/5/8' is visible in the bottom right corner of the photo.



129	GX-B1499/21-C-22020	2022. 6. 22	所检项目合格。		 <p>A photograph showing two workers in a tunnel. They are wearing red hard hats and high-visibility vests with reflective strips. One worker is kneeling and pointing towards a blue piece of equipment, while the other stands nearby. The equipment has a yellow label with Chinese characters. The date '2022/5/8' is visible in the bottom right corner of the photo.</p>
130	GX-B1499/21-C-22021	2022. 6. 22	所检项目合格。		 <p>A photograph showing two workers in a tunnel. They are wearing red hard hats and high-visibility vests with reflective strips. One worker is kneeling and pointing towards a blue piece of equipment, while the other stands nearby. The equipment has a yellow label with Chinese characters. The date '2022/5/8' is visible in the bottom right corner of the photo.</p>

131	GX-B1499/21-C-22022	2022. 6. 22	所检项目合格。	
132	GX-B1499/21-C-22023	2022. 6. 22	所检项目合格。	

133	GX-B1499/21-C-22024	2022. 6. 22	所检项目合格。	
134	GX-B1499/21-C-22025	2022. 6. 22	所检项目合格。	

135	GX-B1499/21-C-22026	2022. 6. 22	所检项目合格。	 <p>A photograph showing two workers in a dark tunnel environment. They are wearing red hard hats and dark work clothes. One worker is standing and looking towards the camera, while the other is crouching down, possibly inspecting equipment. The background shows industrial machinery and pipes. A red circled number '2' is visible on the wall. A yellow timestamp '2022/5/7' is in the bottom right corner.</p>
136	GX-B1499/21-C-22027	2022. 6. 22	所检项目合格。	 <p>A photograph showing two workers in a dark tunnel environment, similar to the one above. They are wearing red hard hats and dark work clothes. One worker is standing and looking towards the camera, while the other is crouching down, possibly inspecting equipment. The background shows industrial machinery and pipes. A red circled number '3' is visible on the wall. A yellow timestamp '2022/5/7' is in the bottom right corner.</p>



137	GX-B1499/21-C-22028	2022. 6. 22	所检项目合格。			
138	GX-B1499/21-C-22029	2022. 6. 22	所检项目合格。			

139	GX-B1499/21-C-22030	2022. 6. 22	所检项目合格。		 <p>2022/5/8</p>	
140	GX-B1515/20-C-22002	2022. 6. 21	所检项目合格。		 <p>2022/5/10</p>	

141	GX-B1328/20-C-22101	2022. 6. 21	检绝缘手套50只， 50只绝缘手套		
142	GX-B1328/20-C-22102	2022. 6. 21	共检绝缘鞋50只， 50只绝缘鞋合		

143	GX-B1306/21-C-22015	2022. 6. 21	所检项目合格。	
144	GX-B1308/21-C-22009	2022. 6. 21	所检项目合格。	



145	GX-B1308/21-C-22010	2022. 6. 21	所检项目合格。	
146	GX-B1499/21-C-22031	2022. 6. 21	所检项目合格。	

147	GX-B1499/21-C-22032	2022. 6. 21	所检项目合格。	
148	GX-B1499/21-C-22033	2022. 6. 21	所检项目合格。	

149	GX-B1499/21-C-22034	2022. 6. 21	所检项目合格。			
150	GX-B1499/21-C-22035	2022. 6. 21	所检项目合格。			

151	GX-B1499/21-C-22036	2022. 6. 21	所检项目合格。		 A photograph showing two workers in a tunnel. One worker is kneeling and looking at a device, while the other stands nearby. The scene is dimly lit with work lights. A yellow timestamp '2022/5/10' is visible in the bottom right corner.	
152	GX-B1499/21-C-22037	2022. 6. 21	所检项目合格。		 A photograph showing two workers in a tunnel. One worker is kneeling and looking at a device, while the other stands nearby. The scene is dimly lit with work lights. A yellow timestamp '2022/5/11' is visible in the bottom right corner.	

153	GX-B1499/21-C-22038	2022. 6. 21	所检项目合格。		
154	GX-B1499/21-C-22039	2022. 6. 21	所检项目合格。		

155	GX-B1495/20-C-22354	2022. 6. 21	检高压开关柜1台, 1台所检项目	
156	GX-B1321/20-C-22150	2022. 6. 21	电力电缆1条, 1条电力电缆所检项目	

157	GX-B1312/20-C-22128~ 22129	2022. 6. 21	检电力变压器2台，2台所检项目	
158	GX-B1385/21-C-22013	2022. 6. 21	所检项目合格。	

159	GX-B1385/21-C-22014	2022. 6. 21	所检项目合格。			
160	GX-B1300/20-C-22002	2022/6/30	所检项目合格			