

序号	报告编号	发布日期	结论	影像资料
5	GX-B1310/21-C-22043	2022.9.8	符合标准要求。	 A photograph showing a worker in a blue uniform and red helmet inspecting a ceiling structure with a flashlight. The date stamp in the bottom right corner of the image is 2022/8/25.
6	GX-B1310/21-C-22044	2022.9.8	符合标准要求。	 A photograph showing two workers in blue uniforms and red helmets standing in a tunnel or underground space. The date stamp in the bottom right corner of the image is 2022/8/26.



19

GX-B1423/20-C-22203

2022/6/17

合格

