


序号	报告编号	发布日期	结论	影像资料
21	GX-B1306/21-Z-22020	9. 19	所检项目合格	
22	GX-B1306/21-Z-22021	9. 19	所检项目合格	

23	GX-B1306/21-Z-22022	9.19	所检项目合格	 A worker wearing a white uniform and a grey helmet is inspecting a large industrial machine. The worker is leaning over the machine, and the date '2022 08 28' is visible in the bottom right corner of the photo.
24	GX-B1306/21-Z-22023	9.19	所检项目合格	 A worker wearing a white uniform and a grey helmet is inspecting a large industrial machine. The worker is standing next to the machine, and the date '2022 08 28' is visible in the bottom right corner of the photo.
25	GX-B1306 / 21-Z-22024	9.2	所检项目合格	 A worker wearing a grey jacket and a white shirt is inspecting a large industrial machine. The worker is standing next to the machine, and the date '2022 09 02' is visible in the bottom right corner of the photo.

26	GX-B1306 / 21-Z-22025	9.2	所检项目合格	
27	GX-B1312/20-Z-22099~22101	2022/9/22	所检项目合格。	
28	GX-B1416/22-Z-22020	2022/9/22	综合判定：合格。	

29	GX-B1416/22-Z-22021	2022/9/22	综合判定：合格。		 <p>2022 09 01</p>	
30	GX-B1416/22-Z-22022	2022/9/22	综合判定：合格。		 <p>2022 09 01</p>	
31	GX-B1416/22-Z-22023	2022/9/22	综合判定：合格。		 <p>2022 09 01</p>	

32	GX-B1416/22-Z-22024	2022/9/22	综合判定：合格。		
33	GX-B1310/21-Z-22069	2022/9/15	符合标准要求。		
34	GX-B1310/21-Z-22070	2022/9/15	符合标准要求。		