

序号	报告编号	发布日期	结论	影像资料
15	GX-B1594/21-9-22036	9.26	(流量)、风压(全压)不	
16	GX-B1594/21-9-22037	9.26	(流量)、风压(全压)不	
17	GX-B1594/21-9-22038	9.26	(流量)、风压(全压)不	

18	GX-B1594/21-9-22039	9.26	<p>(流量)、风压(全压)不判定外,其他</p>  A photograph showing a worker in a red uniform and helmet working on a large pipe. The worker is wearing a red hard hat and a red jacket with reflective stripes. The background is a dark, industrial setting. A vertical timestamp '2022.08.03' is visible on the right side of the image.
19	GX-B1594/21-9-22040	9.26	<p>(流量)、风压(全压)不判定外,其他</p>  A photograph showing a worker in a red uniform and helmet working on a large pipe. The worker is wearing a red hard hat and a red jacket with reflective stripes. The background is a dark, industrial setting. A vertical timestamp '2022.08.03' is visible on the right side of the image.

20	GX-B1343/21-9-22025	2022.9.27	/	 A photograph showing the entrance to the Qingshuijiang Phosphate Mine. The entrance is a large, arched tunnel opening. Above the archway is a sign with the text "清水江磷矿" (Qingshuijiang Phosphate Mine) and "七一(平洞)" (July 1st (Flat Tunnel)). A person in an orange safety suit is standing in the tunnel entrance. There are blue signs on either side of the entrance, one of which says "禁止入内" (No Entry).
21	GX-B1341/21-9-22092	2022.9.28	合格	 A photograph showing a worker in an orange safety suit standing inside a tunnel. The worker is positioned near a large, curved metal structure, possibly a tunnel support or part of the mining equipment. The tunnel walls are dark and rocky.