

序号	报告编号	发布日期	结论	影像资料
71	GX-B1350/21-1-22118	2022. 10. 12	合格	
72	GX-B1350/21-1-22119	2022. 10. 12	合格	
73	GX-B1324/21-1-22010~22021	2022. 10. 12	合格	




74	GX-B1303/21-1-22015	2022/10/13	合格	
75	GX-B1303/21-1-22011	2022/10/13	合格	
76	GX-B1312/20-1-22455	2022/10/13	合格	

77	GX-B1312/20-1-22456~22457	2022/10/13	合格	
78	GX-B1312/20-1-22458	2022/10/13	合格	
79	GX-B1312/20-1-22459	2022/10/13	合格	

80	GX-B1520/20-1-22043	2022/10/13	合格	
81	GX-B1310/21-1-22151	2022. 10. 13	合格	
82	GX-B1310/21-1-22152	2022. 10. 13	合格	

83	GX-B1428/21-1-22152	2022. 10. 13	合格	
84	GX-B1381/20-1-22013	2022. 10. 13	合格	
85	GX-B1423/20-Y-223030	2022年10月11日	合格	

86	GX-B1328/20-1-22120-22121	2022. 10. 10	合格	 A worker in a red hard hat and grey jacket is working on a piece of equipment inside a room. Red safety tape is strung across the floor. A date stamp '2022/10/8' is visible in the bottom right corner of the photo.
87	GX-B1328/20-1-22114	2022. 10. 13	合格	 A worker in a red hard hat and white shirt is kneeling on a concrete surface outdoors, working on a piece of equipment. A date stamp '2022/10/13' is visible in the bottom right corner of the photo.
88	GX-B1328/20-1-22115	2022. 10. 13	合格	 A worker in a red hard hat and white shirt is kneeling on a concrete surface outdoors, working on a piece of equipment. A date stamp '2022/10/13' is visible in the bottom right corner of the photo.

89	GX-B1328/20-1-22116	2022. 10. 13	合格	
90	GX-B1328/20-1-22117	2022. 10. 13	合格	
91	GX-B1328/20-1-22122	2022. 10. 13	合格	

92	GX-B1328/20-1-22123	2022. 10. 13	合格	
93	GX-B1322/21-1-22148~22150	2022. 10. 18	合格	
94	GX-B1548/20-22012	2022/10/19	合格	

95	GX-B1548/20-22013	2022/10/19	合格	
96	GX-B1548/20-22016	2022/10/19	合格	
97	GX-B1534/20-1-22010	2022/10/19	合格	

98	GX-B1534/20-1-22011	2022/10/19	合格	
99	GX-B1539/20-1-22013	2022/10/19	合格	
100	GX-B1307/20-1-22078	2022/10/20	合格	

101	GX-B1307/20-1-22079	2022/10/20	合格	
102	GX-B1350/21-1-22120	2022/10/20	合格	