

序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-Y-22129	2022年12月2日	合格	

2	GX-B1427/21-Y-22129	2022年12月2日	符合标准要求	 <p>A photograph showing a worker in a white protective suit and red helmet working on a large industrial machine. The worker is positioned on the left side of the machine, which has a large vertical cylindrical component. The background shows a factory setting with various metal structures. A yellow timestamp '2022/11/15' is visible in the bottom right corner of the image.</p>
3	GX-B1310/21-Y-22130	2022年12月2日	符合标准要求	 <p>A photograph showing a worker in a white protective suit and red helmet working in a confined space. The worker is wearing a harness and is positioned in the center of the frame, surrounded by vertical metal beams. The lighting is dim, and the worker is using a flashlight. A yellow timestamp '2022/11/16' is visible in the bottom right corner of the image.</p>

4	GX-B1427/21-Y-22130	2022年12月2日	符合标准要求	
5	GX-B1354/20-Y-22014	2022年12月2日	符合规定	

6	GX-B1415/22-Y-22021	2022年12月5日	所检项目合格 
7	GX-B1310/21-Y-22131	2022年12月6日	未发现超过 $\Phi 3\text{mm}$ 当量直径的缺陷。 。 