







序号	报告编号	发布日期	结论	影像资料
30	GX-B1380/20-5-22009	2023年1月19日	合格	 A photograph showing a worker in a dark uniform and a red hard hat standing on a complex metal structure, possibly a staircase or a platform, in an industrial or underground environment. The date stamp at the bottom right of the image reads "2023.1.19".
31	GX-B1380/20-5-22010	2023年1月19日	合格	 A photograph of a worker wearing a blue uniform and a red hard hat, standing on a metal platform or walkway. The worker is looking down at a document or clipboard. The background shows industrial equipment and railings. The date stamp at the bottom right of the image reads "2022.12.14".
32	GX-B1309/21-5-23001	2023/1/19	综合判定：合格	 A photograph of a worker wearing a red hard hat, a blue face mask, and a grey work uniform. The worker is in a narrow, dimly lit tunnel or underground passage, holding a long tool or pipe. The date stamp at the bottom right of the image reads "2023/1/11".

33	GX-B1309/21-5-23002	2023/1/19	综合判定：合格	
34	GX-B1309/21-5-23003	2023/1/19	综合判定：合格	
35	GX-B1309/21-5-23004	2023/1/19	综合判定：合格	

36	GX-B1309/21-5-23005	2023/1/19	综合判定：合格	 <p>A photograph showing a worker in a dark, confined space, likely a tunnel or underground facility. The worker is positioned on a metal ladder, reaching towards a large, dark pipe or structure. The scene is dimly lit, with a bright light source visible in the background. A yellow timestamp '2023/1/12' is visible in the bottom right corner of the image.</p>
37	GX-B1309/21-5-23006	2023/1/19	综合判定：合格	 <p>A photograph of a worker wearing a white protective suit and a red helmet, standing on a metal platform or ladder. The worker is inspecting a large green pipe that runs horizontally across the frame. The background shows a concrete wall and other pipes. A yellow timestamp '2023/1/13' is visible in the bottom right corner of the image.</p>
38	GX-B1309/21-5-23007	2023/1/19	综合判定：合格	 <p>A photograph of a worker in a white protective suit and a red helmet, standing on a metal platform or ladder. The worker is inspecting a large green pipe that runs horizontally across the frame. The background shows a concrete wall and other pipes. A yellow timestamp '2023/1/12' is visible in the bottom right corner of the image.</p>

39	GX-B1500/21-5-23001	2023/1/19	综合判定：合格	
40	GX-B1500/21-5-23002	2023/1/19	综合判定：合格	
41	GX-B1500/21-5-23003	2023/1/19	综合判定：合格	




42	GX-B1500/21-5-23004	2023/1/19	综合判定：合格	
43	GX-B1500/21-5-23005	2023/1/19	综合判定：合格	
44	GX-B1500/21-5-23006	2023/1/19	综合判定：合格	

45	GX-B1500/21-5-23007	2023/1/19	综合判定：合格	
46	GX-B1500/21-5-23008	2023/1/19	综合判定：合格	
47	GX-B1500/21-5-23009	2023/1/19	综合判定：合格	




48	GX-B1500/21-5-23010	2023/1/19	综合判定：合格	
49	GX-B1500/21-5-23011	2023/1/19	综合判定：合格	
50	GX-B1500/21-5-23012	2023/1/19	综合判定：合格	




51	GX-B1500/21-5-23013	2023/1/19	综合判定：合格	 A worker in a white uniform and red helmet is kneeling on a metal platform, working on a large blue industrial machine. The machine has a red handwheel. A yellow date stamp '2023/1/12' is visible in the bottom right corner of the photo.
52	GX-B1500/21-5-23014	2023/1/19	综合判定：合格	 A worker in a white uniform and red helmet is kneeling on a metal platform, working on a large blue industrial machine. The machine has a red handwheel. A yellow date stamp '2023/1/12' is visible in the bottom right corner of the photo.
53	GX-B1500/21-5-23015	2023/1/19	综合判定：合格	 A worker in a white uniform and red helmet is kneeling on a metal platform, working on a large blue industrial machine. The machine has a red handwheel. A yellow date stamp '2023/1/12' is visible in the bottom right corner of the photo.

54	GX-B1500/21-5-23016	2023/1/19	综合判定：合格	
55	GX-B1500/21-5-23017	2023/1/19	综合判定：合格	
56	GX-B1500/21-5-23018	2023/1/19	综合判定：合格	

57	GX-B1500/21-5-23019	2023/1/19	综合判定：合格	
58	GX-B1500/21-5-23020	2023/1/19	综合判定：合格	
59	GX-B1500/21-5-23021	2023/1/19	综合判定：合格	

60	GX-B1500/21-5-23022	2023/1/19	综合判定：合格	
61	GX-B1500/21-5-23023	2023/1/19	综合判定：合格	
62	GX-B1500/21-5-23024	2023/1/19	综合判定：合格	

63	GX-B1500/21-5-23025	2023/1/19	综合判定：合格	
64	GX-B1500/21-5-23026	2023/1/19	综合判定：合格	
65	GX-B1500/21-5-23027	2023/1/19	综合判定：合格	

66	GX-B1500/21-5-23028	2023/1/19	综合判定：合格	
67	GX-B1500/21-5-23029	2023/1/19	综合判定：合格	
68	GX-B1384/16-5-22006	2023年1月30日	合格	

69	GX-B1417/22-5-22010	2023/1/30	综合判定：合格。 。	 <p>2022/12/25</p>
70	GX-B1417/22-5-22011	2023/1/30	综合判定：合格。 。	 <p>2022/12/25</p>
71	GX-B1417/22-5-22012	2023/1/30	综合判定：合格。 。	 <p>2022/12/25</p>

72	GX-B1417/22-5-22013	2023/1/30	综合判定：合格。 。	
73	GX-B1417/22-5-22014	2023/1/30	综合判定：合格。 。	
74	GX-B1417/22-5-22015	2023/1/30	综合判定：合格。 。	

75	GX-B1417/22-5-22016	2023/1/30	综合判定：合格。 。	
76	GX-B1417/22-5-22017	2023/1/30	综合判定：合格。 。	
77	GX-B1417/22-5-22018	2023/1/30	综合判定：合格。 。	


78	GX-B1417/22-5-22019	2023/1/30	综合判定：合格。 。	
79	GX-B1417/22-5-22020	2023/1/30	综合判定：合格。 。	
80	GX-B1417/22-5-22021	2023/1/30	综合判定：合格。 。	


81	GX-B1559/21-5-22015	2023/1/29	所检项目合格。	
82	GX-B1559/21-5-22016	2023/1/29	所检项目合格。	
83	GX-B1310/21-5-22320	2023/1/31	未发现超过 $\Phi 3\text{mm}$ 当量直径的缺陷。 。	

84	GX-B1428/21-5-22042	2023/1/30	无缺陷迹痕显示。 。	 2022/12/29	
85	GX-B1310/21-5-22321	2023/1/31	未发现超过 $\Phi 3\text{mm}$ 当量直径的缺陷。 。	 2022/12/29	
86	GX-B1428/21-5-22043	2023/1/30	无缺陷迹痕显示。 。	 2022/12/29	

87	GX-B1310/21-5-22322	2023/1/31	未发现超过 $\Phi 3\text{mm}$ 当量直径的缺陷。 。	 <p>2022/12/29</p>
88	GX-B1310/21-5-22327	2023/1/31	符合标准要求。	 <p>2022/12/29</p>
89	GX-B1310/21-5-22325	2023/1/31	符合标准要求。	 <p>2022/12/29</p>

90	GX-B1310/21-5-22328	2023/1/31	符合标准要求。	 <p>2022/12/29</p>
91	GX-B1310/21-5-22326	2023/1/31	符合标准要求。	 <p>2022/12/29</p>
92	GX-B1310/21-5-22319	2023/1/31	符合标准要求。	 <p>2022/12/29</p>

93	GX-B1310/21-5-22323	2023/1/31	符合标准要求。	
94	GX-B1427/21-5-22038	2023/1/30	无缺陷磁痕显示。	
95	GX-B1310/21-5-22324	2023/1/31	符合标准要求。	

96	GX-B1427/21-5-22039	2023/1/30	无缺陷磁痕显示。 。	
----	---------------------	-----------	---------------	---