

序号	报告编号	发布日期	结论	影像资料
90	GX-B1310/21-Y-22054	2022年6月2日	合格	
91	GX-B1310/21-Y-22055	2022年6月2日	合格	

92	GX-B1427/21-Y-22055	2022年6月2日		
93	GX-B1310/21-Y-22056	2022年6月2日		

94	GX-B1427/21-Y-22056	2022年6月2日		
95	GX-B1339/21-Y-22001	2022年6月13日	合格	

96	GX-B1339/21-Y-22002	2022年6月13日	合格	
97	GX-B1339/21-Y-22003	2022年6月13日	合格	

98	GX-B1339/21-Y-22004	2022年6月13日	合格	
99	GX-B1321/20-Y-22217~22224	2022年6月16日	合格	

100	GX-B1321/20-Y-22225~22226	2022年6月16日	合格	
101	GX-B1308/21-Y-22010	2022年6月17日	合格	

102	GX-B1499/21-Y-22081	2022年6月17日	合格	 <p>A photograph showing the interior of an industrial tunnel. The walls are painted green and white. There are various pipes, electrical conduits, and equipment visible. A worker in a dark uniform and safety gear is standing on the right side of the tunnel. The floor is dark and appears to be wet or reflective. A yellow date stamp '2022/5/29' is visible in the bottom right corner of the image.</p>
103	GX-B1499/21-Y-22082	2022年6月17日	合格	 <p>A photograph showing a different section of an industrial tunnel. A large blue and red electric motor is prominent in the foreground on the left. The tunnel walls are green and white, with various pipes and equipment. A worker in a dark uniform and safety gear is standing in the center of the tunnel. The floor is dark and reflective. A yellow date stamp '2022/5/29' is visible in the bottom right corner of the image.</p>

104	GX-B1499/21-Y-22083	2022年6月17日	合格	
105	GX-B1323/21-Y-22017	2022年6月16日	合格	

106	GX-B1323/21-Y-22018~22020	2022年6月16日	合格	
107	GX-B1310/21-Y-22061	2022年6月17日	合格	

108	GX-B1428/21-Y-22061	2022年6月17日	合格	 A worker wearing a red hard hat and a white uniform is working on a large, blue industrial machine. The worker is positioned inside the machine, which has a large circular opening. The machine is painted blue and has some red and purple components. A yellow timestamp "2022/6/6" is visible in the bottom right corner of the photo.
109	GX-B1310/21-Y-22062	2022年6月17日	合格	 A worker wearing a red hard hat and a white uniform is working on a large, green industrial machine. The worker is positioned inside the machine, which has a large circular opening. The machine is painted green and has some red and white components. A yellow timestamp "2022/6/6" is visible in the bottom right corner of the photo.

110	GX-B1428/21-Y-22062	2022年6月17日	合格	
111	GX-B1310/21-Y-22063	3022年6月17日	合格	

112	GX-B1310/21-Y-22064	4022年6月17日	合格	
113	GX-B1310/21-Y-22065	5022年6月17日	合格	

114	GX-B1423/20-Y-222476	2022. 6. 20	合格	 A yellow dump truck is parked on a gravel surface. Two workers in hard hats and work clothes are standing near the front of the truck. Several pieces of electronic equipment, including a laptop and a tablet, are laid out on the ground in front of the truck. A yellow date stamp '2022/6/13' is visible in the bottom right corner of the photo.
115	GX-B1423/20-Y-222477	2022. 6. 20	合格	 A yellow dump truck is parked on a gravel surface. Two workers in hard hats and work clothes are standing near the front of the truck. Several pieces of electronic equipment, including a laptop and a tablet, are laid out on the ground in front of the truck. A yellow date stamp '2022/6/13' is visible in the bottom right corner of the photo.

116	GX-B1539/20-Y-22093	2022. 6. 20	合格	
117	GX-B1539/20-Y-22094	2022. 6. 20	合格	

118	GX-B1423/20-Y-222421	2022. 6. 16	合格	
119	GX-B1423/20-Y-222422	2022. 6. 16	合格	

120	GX-B1423/20-Y-222423	2022. 6. 16	合格	
121	GX-B1423/20-Y-222424	2022. 6. 16	合格	

122	GX-B1423/20-Y-222425	2022. 6. 16	合格	
123	GX-B1423/20-Y-222426	2022. 6. 16	合格	

124	GX-B1423/20-Y-222427	2022. 6. 16	合格	
125	GX-B1423/20-Y-222478	2022. 6. 19	合格	

126	GX-B1423/20-Y-222479	2022. 6. 19	合格	
127	GX-B1423/20-Y-222480	2022. 6. 19	合格	

128	GX-B1423/20-Y-222481	2022. 6. 19	合格	
129	GX-B1423/20-Y-222428	2022. 6. 16	合格	

130	GX-B1423/20-Y-222429	2022. 6. 16	合格	 <p>A photograph of a yellow XCMG Z44 dump truck at a construction site. A worker in a white shirt and red helmet stands in the foreground, facing the truck. The truck's bed is raised. The date '2022/5/25' is visible in the bottom right corner of the image.</p>
131	GX-B1423/20-Y-222430	2022. 6. 16	合格	 <p>A photograph of a yellow XCMG Z44 dump truck with the number '03' on its side. Two workers in white shirts and red helmets stand in front of the truck. The date '2022/5/25' is visible in the bottom right corner of the image.</p>

132	GX-B1423/20-Y-222431	2022. 6. 16	合格	 <p>A yellow Masoch dump truck with the number '05' on its side. Two workers are standing in front of the truck. One is wearing a green shirt and the other a white shirt and a red hard hat. There are some equipment cases on the ground in front of them. A yellow timestamp '2022/5/25' is visible in the bottom right corner of the photo.</p>
133	GX-B1423/20-Y-222432	2022. 6. 16	合格	 <p>A yellow Masoch dump truck with the number '06' on its side. Two workers are standing in front of the truck. One is wearing a white shirt and a red hard hat. There are some equipment cases on the ground in front of them. A yellow timestamp '2022/5/25' is visible in the bottom right corner of the photo.</p>

134	GX-B1423/20-Y-222433	2022. 6. 16	合格	 <p>A yellow XBSCH dump truck with the number '07' on its side. Two people are standing in front of the truck, and there are some equipment cases on the ground. A yellow date stamp '2022/5/25' is visible in the bottom right corner of the photo.</p>
135	GX-B1423/20-Y-222434	2022. 6. 16	合格	 <p>A yellow XBSCH dump truck with the number '08' on its side. Two people are standing in front of the truck, and there are some equipment cases on the ground. A yellow date stamp '2022/5/25' is visible in the bottom right corner of the photo.</p>

136	GX-B1423/20-Y-222435	2022. 6. 16	合格	 A yellow XCMG dump truck with the number '09' on its side is parked on a dirt surface. Two men in work clothes and hard hats stand in front of the truck. A toolbox and other equipment are on the ground. A yellow date stamp '2022/5/25' is in the bottom right corner.
137	GX-B1423/20-Y-222436	2022. 6. 16	合格	 A yellow XCMG dump truck with the number '10' on its side is parked on a dirt surface. Two men in work clothes and hard hats stand in front of the truck. A toolbox and other equipment are on the ground. A yellow date stamp '2022/5/25' is in the bottom right corner.

138	GX-B1423/20-Y-222437	2022. 6. 16	合格	
139	GX-B1423/20-Y-222438	2022. 6. 16	合格	

140	GX-B1423/20-Y-222439	2022. 6. 16	合格	
141	GX-B1423/20-Y-222440	2022. 6. 16	合格	

142	GX-B1423/20-Y-222441	2022. 6. 16	合格	
143	GX-B1423/20-Y-222442	2022. 6. 16	合格	

144	GX-B1423/20-Y-222443	2022. 6. 16	合格	
145	GX-B1423/20-Y-222444	2022. 6. 16	合格	

146	GX-B1423/20-Y-222445	2022. 6. 16	合格	
147	GX-B1423/20-Y-222446	2022. 6. 16	合格	

148	GX-B1423/20-Y-222447	2022. 6. 16	合格	 A yellow dump truck is parked on a dirt surface. Two workers in hard hats and work clothes stand in front of the truck. A toolbox and other equipment are on the ground. The date stamp '2022/6/16' is visible in the bottom right corner of the photo.
149	GX-B1423/20-Y-222448	2022. 6. 19	合格	 A yellow dump truck is parked on a dirt surface. Two workers in hard hats and work clothes stand in front of the truck. The date stamp '2022/6/19' is visible in the bottom right corner of the photo.

150	GX-B1423/20-Y-222449	2022. 6. 19	合格	 <p>A yellow TONY dump truck is shown from a side-rear perspective. Two workers in safety gear stand in front of the truck. The truck has 'TONY' written on its side. A yellow date stamp '2022/5/30' is visible in the bottom right corner of the photo.</p>
151	GX-B1423/20-Y-222450	2022. 6. 19	合格	 <p>A yellow TONY dump truck is shown from a side-front perspective. Two workers in safety gear stand in front of the truck. The truck has 'TONY' and 'TL150' written on its side. A yellow date stamp '2022/5/30' is visible in the bottom right corner of the photo.</p>

152	GX-B1423/20-Y-222451	2022. 6. 19	合格	
153	GX-B1423/20-Y-222452	2022. 6. 19	合格	

154	GX-B1423/20-Y-222453	2022. 6. 19	合格	
155	GX-B1423/20-Y-222454	2022. 6. 19	合格	

156	GX-B1423/20-Y-222455	2022. 6. 19	合格	 <p>A yellow dump truck is shown from a side profile. The license plate on the side of the truck reads '360'. A person wearing a white uniform and a red hard hat stands in front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2022/6/30' is visible in the bottom right corner of the photo.</p>
157	GX-B1423/20-Y-222456	2022. 6. 19	合格	 <p>A yellow dump truck is shown from a side profile. The license plate on the side of the truck reads '336'. Two people wearing red hard hats and work clothes stand in front of the truck. One person is holding a clipboard. There is some equipment on the ground in front of them. The truck is parked on a dirt surface. A yellow timestamp '2022/6/30' is visible in the bottom right corner of the photo.</p>

158	GX-B1423/20-Y-222457	2022. 6. 19	合格	 <p>A yellow dump truck with the number 339 on its side. Two workers in blue uniforms and red hard hats stand in front of the truck. A small cart with equipment is on the ground. A yellow timestamp '2022/5/30' is in the bottom right corner.</p>
159	GX-B1423/20-Y-222458	2022. 6. 19	合格	 <p>A yellow dump truck with the number 350 on its side. Two workers in blue uniforms and red hard hats stand in front of the truck. A small cart with equipment is on the ground. A yellow timestamp '2022/5/30' is in the bottom right corner.</p>

160	GX-B1423/20-Y-222459	2022. 6. 19	合格	
161	GX-B1423/20-Y-222460	2022. 6. 19	合格	

162	GX-B1423/20-Y-222461	2022. 6. 19	合格	
163	GX-B1423/20-Y-222462	2022. 6. 19	合格	

164	GX-B1423/20-Y-222463	2022. 6. 19	合格	 <p>A yellow dump truck with the license plate number 3 3557. Two workers in orange safety vests and hard hats stand in front of the truck. A toolbox is on the ground. The date 2022/5/30 is visible in the bottom right corner of the photo.</p>
165	GX-B1423/20-Y-222464	2022. 6. 19	合格	 <p>A yellow dump truck with the license plate number 3 3558. Two workers in blue and grey uniforms stand in front of the truck. A toolbox is on the ground. The date 2022/5/30 is visible in the bottom right corner of the photo.</p>

166	GX-B1423/20-Y-222465	2022. 6. 19	合格	
167	GX-B1423/20-Y-222466	2022. 6. 19	合格	

168	GX-B1423/20-Y-222467	2022. 6. 19	合格	
169	GX-B1423/20-Y-222468	2022. 6. 19	合格	

170	GX-B1423/20-Y-222469	2022. 6. 19	合格	
171	GX-B1423/20-Y-222470	2022. 6. 19	合格	

172	GX-B1423/20-Y-222471	2022. 6. 19	合格	 A yellow dump truck with the number '327' on its side. Two workers in hard hats and work clothes stand in front of the truck. A toolbox is open on the ground in front of them. A yellow date stamp '2022/5/31' is in the bottom right corner.
173	GX-B1423/20-Y-222472	2022. 6. 19	合格	 A yellow dump truck with the number '329' on its side. Two workers in hard hats and work clothes stand in front of the truck. A toolbox is open on the ground in front of them. A yellow date stamp '2022/5/31' is in the bottom right corner.

174	GX-B1423/20-Y-222473	2022. 6. 19	合格	
175	GX-B1423/20-Y-222474	2022. 6. 19	合格	

176	GX-B1423/20-Y-222475	2022. 6. 19	合格	
177	GX-B1539/20-Y-22091	2022. 6. 19	合格	

178	GX-B1539/20-Y-22092	2022. 6. 19	合格	
179	GX-B1559/20-Y-22012	2022年6月20日	合格	

180	GX-B1450/21-Y-22040	2022年6月20日	合格	
181	GX-B1450/21-Y-22041	2022年6月20日	合格	

182	GX-B1450/21-Y-22042	2022年6月20日	合格	
-----	---------------------	------------	----	---