


序号	报告编号	发布日期	结论	影像资料
1	GX-B1415/22-Y-22023	2023年1月3日	所检项目合格	
2	GX-B1521/20-Y-22285	2023年1月3日	所检项目合格	

3	GX-B1521/20-Y-22286	2023年1月3日	所检项目合格	
4	GX-B1515/20-Y-22006	2023年1月4日	所检项目合格	

5	GX-B1328/20-Y-22109~22111	2023年1月4日	所检项目合格	
6	GX-B1306/21-Y-22136	2023年1月5日	所检项目合格	

7	GX-B1328/20-Y-22098--22101	2023年1月4日	所检项目合格	 <p>2022/12/2</p>
8	GX-B1328/20-Y-22107	2023年1月4日	所检项目合格	 <p>2022/12/13</p>

9	GX-B1328/20-Y-22108	2023年1月4日	所检项目合格	
10	GX-B1313/21-Y-22001-22002	2022年1月3日	合格	

11	GX-B1539/22-Y-22190	2022年1月3日	合格	 <p>A yellow wheel loader is parked on a dirt surface. Three people are standing in front of it. The person on the left is wearing a dark jacket and a white cap. The person in the middle is wearing a dark jacket and a white face mask. The person on the right is wearing a light-colored jacket and a red hard hat. The loader has the number '3' on its side. A yellow timestamp '2022/12/13' is visible in the bottom right corner of the photo.</p>
12	GX-B1539/22-Y-22191	2022年1月3日		 <p>A yellow wheel loader is parked on a dirt surface. Three people are standing in front of it. The person on the left is wearing a dark jacket and a white cap. The person in the middle is wearing a dark jacket and a white face mask. The person on the right is wearing a light-colored jacket and a red hard hat. The loader has the number '3' on its side. A yellow timestamp '2022/12/13' is visible in the bottom right corner of the photo.</p>

13	GX-B1312/20-Y-22292-22295	2022年1月3日	合格	 A photograph showing two workers in a confined space. One worker is kneeling on the floor, wearing a blue protective suit and a red helmet, working on a piece of equipment. The other worker is standing, wearing a white protective suit and a red helmet, holding a red cable. The date '2022/12/2' is visible in the bottom right corner of the photo.
14	GX-B1308/21-Y-22015	2022年1月3日	合格	 A photograph showing three workers in a dark environment, likely a tunnel or confined space. They are wearing protective gear, including helmets with lights and reflective vests. They are working on a large, dark pipe or structure. The scene is dimly lit, with the workers' lights providing the main illumination.

15	GX-B1499/21-Y-22139	2022年1月3日	合格	
16	GX-B1499/21-Y-22140	2022年1月3日	合格	

17	GX-B1499/21-Y-22141	2022年1月3日	合格	
18	GX-B1416/22-Y-22044	2023年1月3日	所检项目合格	

19	GX-B1416/22-Y-22045	2023年1月3日	所检项目合格	 <p>2022/12/3</p>
20	GX-B1416/22-Y-22046	2023年1月3日	所检项目合格	 <p>2022/12/3</p>

21	GX-B1423/20-Y-223416	2023年1月3日	所检项目合格	
22	GX-B1423/20-Y-223417	2023年1月3日	所检项目合格	

23	GX-B1423/20-Y-223418	2023年1月3日	所检项目合格	
24	GX-B1499/21-Y-22134	2023年1月3日	所检项目合格	

25	GX-B1499/21-Y-22135	2023年1月3日	所检项目合格	
26	GX-B1499/21-Y-22136	2023年1月3日	所检项目合格	

27	GX-B1423/20-Y-223414	2023年1月3日	所检项目合格	
28	GX-B1423/20-Y-223415	2023年1月4日	所检项目合格	

29	GX-B1561/20-Y-22008	2023年1月5日	所检项目合格	
30	GX-B1417/22-Y-22098	2023年1月5日	所检项目合格	



31	GX-B1417/22-Y-22099	2023年1月5日	所检项目合格	
32	GX-B1417/22-Y-22100	2023年1月5日	所检项目合格	

33	GX-B1417/22-Y-22101	2023年1月5日	所检项目合格	 A photograph showing three individuals wearing winter jackets, gloves, and masks standing in front of a white SUV inside a garage. The SUV has a license plate that reads "京K 9R001". A yellow timestamp "2022/12/14" is visible in the bottom right corner of the image.
34	GX-B1417/22-Y-22102	2023年1月5日	所检项目合格	 A photograph showing two individuals wearing winter jackets and masks standing in front of a white SUV outdoors in a parking lot. The SUV has a license plate that reads "京K 9R001". A yellow timestamp "2022/12/14" is visible in the bottom right corner of the image.

35	GX-B1417/22-Y-22103	2023年1月5日	所检项目合格	
36	GX-B1417/22-Y-22104	2023年1月5日	所检项目合格	

37	GX-B1559/22-Y-22019	2023年1月4日	合格	 <p>A worker wearing a red protective suit and a red helmet with a headlamp is operating a piece of machinery in a dark environment. The worker is holding a tool or control lever. A yellow timestamp '2022/12/4' is visible in the bottom right corner of the image.</p>
38	GX-B1539/22-Y-22192	2023年1月4日	合格	 <p>Three workers wearing white protective suits and red helmets are standing in front of a large yellow mining truck. The truck is parked in a large industrial facility. A yellow timestamp '2022/12/15' is visible in the bottom right corner of the image.</p>

39	GX-B1539/22-Y-22193	2023年1月4日	合格	
40	GX-B1539/22-Y-22194	2023年1月4日	合格	

41	GX-B1539/22-Y-22195	2023年1月4日	合格	
42	GX-B1539/22-Y-22196	2023年1月4日	合格	



43	GX-B1539/22-Y-22197	2023年1月4日	合格	
44	GX-B1539/22-Y-22198	2023年1月4日	合格	

45	GX-B1539/22-Y-22199	2023年1月4日	合格	
46	GX-B1339/21-Y-22022	2023年1月6日	所检项目合格	

47	GX-B1300/20-Y-22013	2023年1月6日	所检项目合格	
48	GX-B1300/20-Y-22014	2023年1月6日	所检项目合格	

49	GX-B1415/22-Y-22024	2023年1月6日	所检项目合格	
50	GX-B1415/22-Y-22025	2023年1月6日	所检项目合格	

51	GX-B1424/20-Y-22009	2023年1月6日	所检项目合格	
52	GX-B1328/20-Y-22093--22097	2023年1月6日	所检项目合格	

53	GX-B1310/21-Y-22143	2023年1月6日	合格	
54	GX-B1427/21-Y-22143	2023年1月6日	合格	

55	GX-B1310/21-Y-22144	2023年1月6日	合格	
56	GX-B1427/21-Y-22144	2023年1月6日	合格	

57	GX-B1424/20-Y-23001	2023年1月6日	合格	
58	GX-B1310/21-Y-23001	2023年1月6日	合格	

59	GX-B1559/22-Y-22018	2023年1月4日	所检项目合格	
----	---------------------	-----------	--------	---