

序号	报告编号	发布日期	结论	影像资料
265	GX-B1423/20-Y-233203	2023年6月12日	综合判定：合格	

266	GX-B1423/20-Y-233204	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

267	GX-B1423/20-Y-233205	2023年6月12日	综合判定：合格	 A photograph showing a worker wearing a red hard hat and a light-colored jacket, operating a piece of machinery. The worker is seated and looking towards the right. The machinery has a steering wheel and various controls. A yellow timestamp '2023/5/15' is visible in the bottom right corner of the photo.
-----	----------------------	------------	---------	--

268	GX-B1423/20-Y-233206	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

269	GX-B1423/20-Y-233207	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

270	GX-B1423/20-Y-233208	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

271	GX-B1423/20-Y-233209	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

272	GX-B1423/20-Y-233210	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

273	GX-B1423/20-Y-233211	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

274	GX-B1423/20-Y-233212	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

275	GX-B1423/20-Y-233213	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

276	GX-B1423/20-Y-233214	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

277	GX-B1423/20-Y-233215	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

278	GX-B1423/20-Y-233216	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

279	GX-B1423/20-Y-233217	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

280	GX-B1423/20-Y-233218	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---

281	GX-B1423/20-Y-233219	2023年6月12日	综合判定：合格	 A yellow TONLY dump truck with the number '58' on its side. Two workers wearing red hard hats and safety vests are standing in front of the truck. The truck is parked on a dirt surface. A date stamp '2023/5/15' is visible in the bottom right corner of the image.
282	GX-B1423/20-Y-233220	2023年6月11日	综合判定：合格	 A yellow TONLY dump truck with the number '8291' on its side. One worker wearing a red hard hat and safety vest is standing in front of the truck. The truck is parked on a dirt surface. A date stamp '2023/5/15' is visible in the bottom right corner of the image.

283	GX-B1423/20-Y-233221	2023年6月11日	综合判定：合格	
284	GX-B1423/20-Y-233222	2023年6月11日	综合判定：合格	

285	GX-B1423/20-Y-233223	2023年6月11日	综合判定：合格	 <p>A yellow TONLY dump truck is parked on a gravel surface. Two workers in white shirts and red hard hats stand in front of the truck. The truck has the number '8231' on its side. A yellow timestamp '2023/6/15' is visible in the bottom right corner of the photo.</p>
286	GX-B1423/20-Y-233224	2023年6月11日	综合判定：合格	 <p>A yellow TONLY dump truck is parked on a dirt surface. Three workers are standing in front of the truck: one in an orange jumpsuit, one in a white shirt and red hard hat, and one in a blue shirt. The truck has the number '8231' on its side. A yellow timestamp '2023/6/15' is visible in the bottom right corner of the photo.</p>

287	GX-B1423/20-Y-233225	2023年6月11日	综合判定：合格	
288	GX-B1423/20-Y-233226	2023年6月11日	综合判定：合格	

289	GX-B1423/20-Y-233227	2023年6月11日	综合判定：合格	
290	GX-B1423/20-Y-233228	2023年6月11日	综合判定：合格	

291	GX-B1423/20-Y-233229	2023年6月11日	综合判定：合格	
292	GX-B1423/20-Y-233230	2023年6月11日	综合判定：合格	

293	GX-B1423/20-Y-233231	2023年6月11日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt surface. The truck has the number '8279' painted on its side. A person in a white shirt and blue pants is standing near the front wheel. The date '2023/5/16' is visible in the bottom right corner of the photo.
294	GX-B1423/20-Y-233232	2023年6月11日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt surface. The truck has the number '952' painted on its side. A person in a white shirt and red hard hat is standing near the front wheel, looking at a clipboard. The date '2023/5/16' is visible in the bottom right corner of the photo.

295	GX-B1423/20-Y-233233	2023年6月11日	综合判定：合格	
296	GX-B1423/20-Y-233234	2023年6月11日	综合判定：合格	

297	GX-B1423/20-Y-233235	2023年6月11日	综合判定：合格	
298	GX-B1423/20-Y-233236	2023年6月11日	综合判定：合格	

299	GX-B1423/20-Y-233237	2023年6月11日	综合判定：合格	
300	GX-B1423/20-Y-233238	2023年6月11日	综合判定：合格	

301	GX-B1423/20-Y-233239	2023年6月11日	综合判定：合格	
302	GX-B1423/20-Y-233240	2023年6月11日	综合判定：合格	

303	GX-B1423/20-Y-233241	2023年6月11日	综合判定：合格	
304	GX-B1423/20-Y-233242	2023年6月11日	综合判定：合格	

305	GX-B1423/20-Y-233243	2023年6月11日	综合判定：合格	
306	GX-B1423/20-Y-233244	2023年6月11日	综合判定：合格	

307	GX-B1423/20-Y-233245	2023年6月11日	综合判定：合格	
308	GX-B1495/20-Y-231299~231314	2023年6月10日	本次共检高压开关设备16台，16台高压开关设备所检项目合格。 。	

309	GX-B1495/20-Y-231315~ 231333	2023年6月10日	本次共检高压开关设备19台，19台高压开关设备所检项目合格。	
310	GX-B1495/20-Y-231395~ 231407	2023年6月10日	本次共检高压开关设备13台，13台高压开关设备所检项目合格。	

311	GX-B1495/20-Y-231390~231394	2023年6月10日	本次共检高压交流断路器5台，5台所检项目合格。	
312	GX-B1547/20-Y-23252~23255	2023年6月10日	本次共检继电保护装置4台，4台所检项目合格。	

313	GX-B1522/20-Y-23091	2023年6月12日	所检项目合格。	
314	GX-B1522/20-Y-23092	2023年6月12日	所检项目合格。	

315	GX-B1522/20-Y-23093	2023年6月12日	所检项目合格。	 <p>A yellow JCB S-1172 telehandler is shown in an outdoor setting. A worker wearing a red helmet and a light-colored safety vest is standing next to the machine, inspecting it. The machine has a large hydraulic arm and various attachments. A yellow timestamp '2023/6/6' is visible in the bottom right corner of the photo.</p>
316	GX-B1423/20-Y-232930	2023年6月12日	综合判定：合格	 <p>A yellow dump truck is shown in an outdoor setting. A worker wearing a red helmet and a light-colored safety vest is standing next to the truck, inspecting it. The truck has a large dump body and multiple axles. A yellow timestamp '2023/6/4' is visible in the bottom right corner of the photo.</p>

317	GX-B1423/20-Y-232931	2023年6月12日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. A person in a light-colored uniform and a red hard hat is standing next to the truck, inspecting the rear wheel area. The truck has "同力重工" (Tongli Heavy Industry) and "TH-400" written on its side. The background is a clear blue sky and a sandy or dusty ground. A yellow timestamp "2023/5/4" is visible in the bottom right corner of the image.
318	GX-B1423/20-Y-232932	2023年6月12日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. A person in a light-colored uniform and a red hard hat is standing next to the truck, inspecting the rear wheel area. The truck has "同力重工" (Tongli Heavy Industry) and "TH-400" written on its side. The background is a clear blue sky and a sandy or dusty ground. A yellow timestamp "2023/5/4" is visible in the bottom right corner of the image.

319	GX-B1423/20-Y-232933	2023年6月12日	综合判定：合格	
320	GX-B1423/20-Y-232934	2023年6月12日	综合判定：合格	

321	GX-B1423/20-Y-232935	2023年6月12日	综合判定：合格	
322	GX-B1423/20-Y-232936	2023年6月12日	综合判定：合格	

323	GX-B1423/20-Y-232937	2023年6月12日	综合判定：合格	
324	GX-B1423/20-Y-232938	2023年6月12日	综合判定：合格	

325	GX-B1423/20-Y-232939	2023年6月12日	综合判定：合格	
326	GX-B1423/20-Y-232940	2023年6月12日	综合判定：合格	

327	GX-B1423/20-Y-232941	2023年6月12日	综合判定：合格	
328	GX-B1423/20-Y-232942	2023年6月12日	综合判定：合格	

329	GX-B1423/20-Y-232943	2023年6月12日	综合判定：合格	
330	GX-B1423/20-Y-232944	2023年6月12日	综合判定：合格	

331	GX-B1423/20-Y-232945	2023年6月12日	综合判定：合格	
332	GX-B1423/20-Y-232946	2023年6月12日	综合判定：合格	

333	GX-B1423/20-Y-232947	2023年6月12日	综合判定：合格	
334	GX-B1423/20-Y-232948	2023年6月12日	综合判定：合格	

335	GX-B1423/20-Y-232949	2023年6月12日	综合判定：合格	
336	GX-B1423/20-Y-232950	2023年6月12日	综合判定：合格	

337	GX-B1423/20-Y-232951	2023年6月12日	综合判定：合格	
338	GX-B1423/20-Y-232952	2023年6月12日	综合判定：合格	

339	GX-B1423/20-Y-232953	2023年6月12日	综合判定：合格	
340	GX-B1423/20-Y-232954	2023年6月12日	综合判定：合格	

341	GX-B1423/20-Y-232955	2023年6月12日	综合判定：合格	
342	GX-B1423/20-Y-232956	2023年6月12日	综合判定：合格	

343	GX-B1423/20-Y-232957	2023年6月12日	综合判定：合格	
344	GX-B1423/20-Y-233189	2023年6月12日	综合判定：合格	

345	GX-B1423/20-Y-233190	2023年6月12日	综合判定：合格	
346	GX-B1423/20-Y-233191	2023年6月12日	综合判定：合格	

347	GX-B1423/20-Y-233192	2023年6月12日	综合判定：合格	
348	GX-B1423/20-Y-233193	2023年6月12日	综合判定：合格	

349	GX-B1423/20-Y-233194	2023年6月12日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. The side of the truck has the identification number 'H3125' written in white. Two workers wearing hard hats and safety vests are standing in front of the truck. A yellow date stamp '2023/6/20' is visible in the bottom right corner of the photo.
350	GX-B1423/20-Y-233195	2023年6月12日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. The side of the truck has the identification number 'H3125' written in white. Two workers wearing hard hats and safety vests are standing in front of the truck. A yellow date stamp '2023/6/20' is visible in the bottom right corner of the photo.

351	GX-B1423/20-Y-233196	2023年6月12日	综合判定：合格	
352	GX-B1423/20-Y-233197	2023年6月12日	综合判定：合格	

353	GX-B1423/20-Y-233198	2023年6月12日	综合判定：合格	
354	GX-B1423/20-Y-233199	2023年6月12日	综合判定：合格	

355	GX-B1423/20-Y-233200	2023年6月12日	综合判定：合格	
356	GX-B1423/20-Y-233201	2023年6月12日	综合判定：合格	

357	GX-B1423/20-Y-233202	2023年6月12日	综合判定：合格	
358	GX-B1423/20-Y-232918	2023年6月12日	综合判定：合格	

359	GX-B1423/20-Y-232919	2023年6月12日	综合判定：合格	 <p>A photograph of a yellow XCMG dump truck parked on a dirt surface. The truck has the license plate 'M-4123' and the text '徐工重卡' (XCMG Heavy Duty Truck) on its side. A worker wearing a blue hard hat and a high-visibility yellow vest stands next to the truck. A yellow timestamp '2023/5/3' is visible in the bottom right corner of the image.</p>
360	GX-B1423/20-Y-232920	2023年6月12日	综合判定：合格	 <p>A photograph of a yellow XCMG dump truck parked on a dirt surface. The truck has the license plate 'M-4123' and the text '徐工重卡' (XCMG Heavy Duty Truck) on its side. A worker wearing a blue hard hat and a high-visibility yellow vest stands next to the truck. A yellow timestamp '2023/5/3' is visible in the bottom right corner of the image.</p>

361	GX-B1423/20-Y-232921	2023年6月12日	综合判定：合格	 A yellow XCMG M-4122 dump truck is parked on a dirt surface at a construction site. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has '徐工重卡' (XCMG Heavy Duty) and 'M-4122' written on it. A yellow timestamp '2023/5/3' is visible in the bottom right corner of the photo.
362	GX-B1423/20-Y-232922	2023年6月12日	综合判定：合格	 A yellow XCMG dump truck is parked on a dirt surface at a construction site. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has '徐工重卡' (XCMG Heavy Duty) written on it. A yellow timestamp '2023/5/3' is visible in the bottom right corner of the photo.

363	GX-B1423/20-Y-232923	2023年6月12日	综合判定：合格	
364	GX-B1423/20-Y-232924	2023年6月12日	综合判定：合格	

365	GX-B1423/20-Y-232927	2023年6月12日	综合判定：合格	
366	GX-B1423/20-Y-232928	2023年6月12日	综合判定：合格	

367	GX-B1423/20-Y-232929	2023年6月12日	综合判定：合格	
-----	----------------------	------------	---------	---