

序号	报告编号	发布日期	结论	影像资料
253	GX-B1363/22-A-23530	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
254	GX-B1363/22-A-23531	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
255	GX-B1363/22-A-23528	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
256	GX-B1363/22-A-23529	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
257	GX-B1363/22-A-23520	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
258	GX-B1363/22-A-23481	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
259	GX-B1470/23-A-23005	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
260	GX-B1509/20-A-23020	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
261	GX-B1509/20-A-23018	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
262	GX-B1509/20-A-23019	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
263	GX-B1509/20-A-23021	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
264	GX-B1364/22-A-231064	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
265	GX-B1364/22-A-231062	2023/11/17	所检项目合格。	 A photograph showing two men in light-colored lab coats working in a laboratory. One man is standing on the left, looking towards the right. The other man is on the right, wearing gloves and operating a piece of equipment that has a reflective surface. A date stamp '2023/11/09' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
266	GX-B1364/22-A-231065	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
267	GX-B1364/22-A-231066	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
268	GX-B1364/22-A-231068	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
269	GX-B1364/22-A-231070	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
270	GX-B1364/22-A-231072	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
271	GX-B1364/22-A-231073	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
272	GX-B1364/22-A-231063	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
273	GX-B1364/22-A-231087	2023/11/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
274	GX-B1367/22-A-23102	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
275	GX-B1364/22-A-231135	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
276	GX-B1364/22-A-231136	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
277	GX-B1364/22-A-231137	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
278	GX-B1364/22-A-231098	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
279	GX-B1364/22-A-231099	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
280	GX-B1364/22-A-231096	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
281	GX-B1364/22-A-231097	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
282	GX-B1365/20-A-23094	2023/11/20	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
283	GX-B1366/20-A-23126	2023/11/20	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
284	GX-B1365/20-A-23093	2023/11/20	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
285	GX-B1366/20-A-23123	2023/11/20	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
286	GX-B1538/22-A-23038	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
287	GX-B1538/22-A-23039	2023/11/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
288	GX-B1363/22-A-23532	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
289	GX-B1363/22-A-23523	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
290	GX-B1363/22-A-23496	2023/11/21	所检项目合格。	 A photograph showing two men in light-colored work jackets inspecting a large, industrial metal furnace or boiler. The furnace has a tall, cylindrical chimney pipe extending from the top. The men are standing on either side of the furnace, looking at it intently. The furnace has several yellow warning triangles on its surface. The background shows a window with a view of trees outside. A date stamp '2023/11/08' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
291	GX-B1363/22-A-23495	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
292	GX-B1364/22-A-231103	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
293	GX-B1364/22-A-231095	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
294	GX-B1364/22-A-231094	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
295	GX-B1364/22-A-231091	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
296	GX-B1364/22-A-231090	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
297	GX-B1364/22-A-231089	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
298	GX-B1364/22-A-231102	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
299	GX-B1364/22-A-231101	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
300	GX-B1364/22-A-231100	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
301	GX-B1364/22-A-231116	2023/11/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
302	GX-B1363/22-A-23537	2023/11/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
303	GX-B1363/22-A-23536	2023/11/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
304	GX-B1363/22-A-23535	2023/11/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
305	GX-B1363/22-A-23526	2023/11/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
306	GX-B1363/22-A-23525	2023/11/22	所检项目合格。	