





序号	报告编号	发布日期	结论	影像资料
1	GX-B1301/23-5-23012	2024. 1. 2	合格	
2	GX-B1517/20-5-23032	2024. 1. 2	综合判定：合格	



3	GX-B1517/20-5-23033	2024. 1. 2	综合判定：合格	 <p>2023/12/11</p>
4	GX-B1517/20-5-23034	2024. 1. 2	综合判定：合格	 <p>2023. 12. 13</p>

5	GX-B1517/20-5-23035	2024. 1. 2	综合判定：合格	
6	GX-B1358/21-5-23005	2024. 1. 3	所检项目合格。	

7	GX-B1350/21-5-23067	2024/1/4	所检项目合格。	 <p>2023/12/9</p>
8	GX-B1350/21-5-23068	2024/1/4	本次共检接地装置4处，4处接地装置所检项目合格。	 <p>2023/12/10</p>

9	GX-B1428/21-5-23041	2024. 1. 2	无缺陷迹痕显示。		 <p>2023. 12. 13</p>	
10	GX-B1428/21-5-23042	2024. 1. 2	无缺陷迹痕显示。		 <p>2023. 12. 13</p>	



11	GX-B1310/21-5-23309	2024. 1. 2	符合标准要求。	
12	GX-B1310/21-5-23310	2024. 1. 2	符合标准要求。	

13	GX-B1310/21-5-23311	2024. 1. 2	符合标准要求。	 <p>2023. 12. 13</p>
14	GX-B1310/21-5-23312	2024. 1. 2	符合标准要求。	 <p>2023. 12. 13</p>

15	GX-B1310/21-5-23313	2024. 1. 2	符合标准要求。	
16	GX-B1310/21-5-23314	2024. 1. 2	符合标准要求。	

17	GX-B1427/21-5-23023	2024. 1. 2	符合标准要求。	 <p>2023. 12. 13</p>
18	GX-B1427/21-5-23024	2024. 1. 2	符合标准要求。	 <p>2023. 12. 13</p>

19	GX-B1424/20-5-23057	2024/1/4	依据NB/T 10176-2019单轨吊车所检项目合格。			
20	GX-B1424/20-5-23058	2024/1/4	依据NB/T 10176-2019单轨吊车所检项目合格。			


21	GX-B1358/21-5-23005	2024. 1. 3	所检项目合格。	
22	GX-B1428/21-5-23039	2024. 1. 4	无缺陷迹痕显示	

23	GX-B1428/21-5-23040	2024. 1. 4	无缺陷迹痕显示	
24	GX-B1310/21-5-23307	2024. 1. 4	符合标准要求	

25	GX-B1310/21-5-23308	2024. 1. 4	符合标准要求	
26	GX-B1359/21-5-23159	2024. 1. 5	所检项目合格。	

27	GX-B1359/21-5-23160	2024. 1. 5	所检项目合格。	
28	GX-B1359/21-5-23161~23183	2024. 1. 5	本次共检矿用隔爆型照明信号综合保护装置23台，23台矿用隔爆型照明信号综合保护装置所检项目合格。	

29	GX-B1350/21-5-23069	2023. 1. 5	所检项目合格。	
30	GX-B1350/21-5-23070	2023. 1. 5	接地装置3处，3处所检项目	

31	GX-B1350/21-5-23071	2023. 1. 5	所检项目合格。	
----	---------------------	------------	---------	---