







序号	报告编号	发布日期	结论	影像资料
28	GX-B1598/21-6-24001	2024/2/7	实测钢丝绳有效截面积损失百分比最大为0.54%，小于5%为正常。	
29	GX-B1598/21-6-24002	2024/2/7	实测钢丝绳有效截面积损失百分比最大为0.67%，小于5%为正常。	

30	GX-B1598/21-6-24003	2024/2/7	实测钢丝绳有效截面积损失百分比最大为0.62%，小于5%为正常。	 <p>2024 01 03</p>
31	GX-B1598/21-6-24004	2024/2/7	实测钢丝绳有效截面积损失百分比最大为0.57%，小于5%为正常。	 <p>2024 01 03</p>
32	GX-B1598/21-6-24005	2024/2/7	实测钢丝绳有效截面积损失百分比最大为0.53%，小于5%为正常。	 <p>2024 01 04</p>

33	GX-B1598/21-6-24006	2024/2/7	实测钢丝绳有效截面积损失百分比最大为0.54%，小于5%为正常。	 <p>2024 01 04</p>
34	GX-B1598/21-6-24007	2024/2/7	实测钢丝绳有效截面积损失百分比最大为0.54%，小于5%为正常。	 <p>2024 01 03</p>
35	GX-B1598/21-6-24008	2024/2/7	实测钢丝绳有效截面积损失百分比最大为0.60%，小于5%为正常。	 <p>2024 01 03</p>

36	GX-B1328/20-6-24020	2.6	所检项目合格	 <p>A worker wearing a red helmet and dark clothing is kneeling on a concrete surface, testing a transformer. A bucket of oil is placed in front of the transformer. The background shows a parking lot with several white cars and a building. A red date stamp '2024 01 21' is visible in the bottom right corner of the photo.</p>
37	GX-B1328/20-6-24021	2.6	所检项目合格	 <p>A worker wearing a red helmet and dark clothing is kneeling on a concrete surface, testing a transformer. A bucket of oil is placed in front of the transformer. The background shows a parking lot with several white cars and a building. A red date stamp '2024 01 21' is visible in the bottom right corner of the photo.</p>
38	GX-B1328/20-6-24022	2.6	所检项目合格	 <p>A worker wearing a red helmet and dark clothing is kneeling on a concrete surface, testing a transformer. A bucket of oil is placed in front of the transformer. The background shows a parking lot with several white cars and a building. A red date stamp '2024 01 21' is visible in the bottom right corner of the photo.</p>

39	GX-B1328/20-6-24023	2.6	所检项目合格	
40	GX-B1424/20-6-24005	2024/2/18	依据NB/T 10176-2019单轨吊车综合判定合格。	
41	GX-B1451/20-6-24006~24010	2024/2/18	所检项目合格	

42	GX-B1424/20-6-24003	2024/2/18	依据NB/T 10176-2019单轨吊车综合判定合格。		 <p>2024 01 12</p>
43	GX-B1424/20-6-24004	2024/2/18	依据NB/T 10176-2019单轨吊车综合判定合格。		 <p>2024 01 12</p>
44	GX-B1451/20-6-24002~24005	2024/2/18	所检项目合格		 <p>2024 01 21</p>

45	GX-B1520/20-6-24015	2024/2/7	综合判定合格		
46	GX-B1520/20-6-24016	2024/2/7	综合判定合格		
47	GX-B1303/21-6-24002	2024/2/19	综合判定合格		