



















序号	报告编号	发布日期	结论	影像资料
21	GX-B1495/20-P-24001-24019	2024. 2. 27	本次共检高压开关设备19台，19台高压开关设备所检项目合格。	
22	GX-B1495/20-P-24020-24034	2024. 2. 27	本次共检高压开关设备15台，15台高压开关设备所检项目合格。	
23	GX-B1495/20-P-24035-24038	2024. 2. 27	本次共检高压开关设备4台，4台高压开关设备所检项目合格。	

24	GX-B1495/20-P-24039-24046	2024. 2. 27	本次共检高压开关设备8台，8台高压开关设备所检项目合格。		
25	GX-B1495/20-P-24047-24049	2024. 2. 27	本次共检高压开关设备3台，3台高压开关设备所检项目合格。		
26	GX-B1495/20-P-24050-24054	2024. 2. 27	本次共检高压开关设备5台，5台高压开关设备所检项目合格。		
27	GX-B1495/20-P-24055-24060	2024. 2. 27	本次共检高压开关设备6台，6台高压开关设备所检项目合格。		

28	GX-B1495/20-P-24061-24063	2024. 2. 27	本次共检高压开关设备3台，3台高压开关设备所检项目合格。	
29	GX-B1404/20-P-24001	2024. 2. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
30	GX-B1301/23-P-24002	2024. 2. 26	所检项目合格	
31	GX-B1321/20-P-24001~24007	2024. 2. 26	本次共检电力电缆7条，7条电力电缆所检项目合格。	

32	GX-B1321/20-P-24008~24015	2024. 2. 26	本次共检电力电缆8条，8条电力电缆所检项目合格。	
33	GX-B1321/20-P-24016~24024	2024. 2. 26	本次共检电力电缆9条，9条电力电缆所检项目合格。	
34	GX-B1321/20-P-24025~24029	2024. 2. 26	本次共检电力电缆5条，5条电力电缆所检项目合格。	
35	GX-B1404/20-P-24002	2024. 2. 26	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

36	GX-B1559/22-P-24028	2023. 2. 29	所检项目合格	 A worker wearing a red hard hat and a blue face mask is operating a forklift. The forklift is positioned in a warehouse or industrial setting, with a green tarp visible in the background. The date stamp in the bottom right corner of the image is 2024.1.18.
37	GX-B1559/22-P-24029	2023. 2. 29	所检项目合格	 A worker wearing a red hard hat and a white jacket is operating a piece of machinery. The worker is positioned in an industrial setting, and the date stamp in the bottom right corner of the image is 2024.1.18.
38	GX-B1559/22-P-24030	2023. 2. 29	所检项目合格	 A worker wearing a red hard hat and a white jacket is inspecting a piece of machinery. The worker is positioned in an industrial setting, and the date stamp in the bottom right corner of the image is 2024.1.21.
39	GX-B1559/22-P-24031	2023. 2. 29	所检项目合格	 A worker wearing a red hard hat and a dark jacket is inspecting a piece of machinery. The worker is positioned in an industrial setting, and the date stamp in the bottom right corner of the image is 2024.1.21.

40	GX-B1495/20-P-24068-24070	2024. 2. 29	本次共检GIS设备3台，3台GIS设备所检项目合格。	
41	GX-B1495/20-P-24064-24067	2024. 2. 29	本次共检GIS设备3台，3台GIS设备所检项目合格。	
42	GX-B1547/20-P-24001-24005	2024. 2. 29	本次共检继电保护装置5台，5台继电保护装置所检项目合格。	
43	GX-B1547/20-P-24006-24009	2024. 2. 29	本次共检继电保护装置4台，4台继电保护装置所检项目合格。	