


序号	报告编号	发布日期	结论	影像资料
65	GX-B1322/21-1-24111~24116	2024. 4. 8	本次共检验电力电缆6条，6条所检项目合格	
66	GX-B1322/21-1-24117~24130	2024. 4. 8	本次共检验电力电缆14条，14条所检项目合格	

67	GX-B1321/20-1-24017~24029	2024. 4. 8	所检项目合格	
68	GX-B1321/20-1-24030~24036	2024. 4. 8	所检项目合格	

69	GX-B1306/23-1-24005	2024. 4. 9	所检项目合格	
70	GX-B1306/23-1-24006	2024. 4. 9	所检项目合格	

71	GX-B1306/23-1-24007	2024. 4. 9	所检项目合格	
72	GX-B1306/23-1-24008	2024. 4. 9	所检项目合格	

73	GX-B1495/20-1-24057~24074	2024. 4. 9	本次共检高压防爆开关设备18台，18台高压防爆开关设备所检项目合格	
74	GX-B1495/20-1-24075~24078	2024. 4. 9	本次共检高压防爆开关设备4台，4台高压防爆开关设备所检项目合格	

75	GX-B1495/20-1-24079~24100	2024. 4. 9	本次共检高压开关设备22台，22台高压开关设备所检项目合格	
76	GX-B1495/20-1-24101~24116	2024. 4. 9	本次共检高压开关设备16台，16台高压开关设备所检项目合格	

77	GX-B1495/20-1-24117~24118	2024. 4. 9	本次共检高压开关设备 2台，2台高压开关设备 所检项目合格	
78	GX-B1547/20-1-24001~24003	2024. 4. 8	本次共检继电保护装置 3台，3台所检项目 合格	

79	GX-B1547/20-1-24004~24006	2024. 4. 8	本次共检继电保护装置3台，3台所检项目合格	
80	GX-B1310/21-1-24045	2024. 4. 8	符合标准要求	

81	GX-B1301/23-1-24003	2024. 4. 7	综合判定:合格	
82	: GX-B1301/23-1-24002	2024. 4. 7	综合判定:合格	

83	GX-B1301/23-1-24001	2024. 4. 7	综合判定:合格	
84	GX-B1300/23-1-24003	2024. 4. 7	综合判定:合格	

85	GX-B1495/20-1-24057~24074	2024. 4. 9	本次共检高压防爆开关设备18台，18台高压防爆开关设备所检项目合格	
86	GX-B1495/20-1-24075~24078	2024. 4. 9	本次共检高压防爆开关设备4台，4台高压防爆开关设备所检项目合格	

87	GX-B1495/20-1-24079~24100	2024. 4. 9	本次共检高压开关设备22台，22台高压开关设备所检项目合格	
88	GX-B1495/20-1-24101~24116	2024. 4. 9	本次共检高压开关设备16台，16台高压开关设备所检项目合格	

89	GX-B1495/20-1-24117~24118	2024. 4. 9	本次共检高压开关设备 2台，2台高压开关设备 所检项目合格	
90	GX-B1495/20-1-24119~24120	2024. 4. 9	本次共检高压开关设备 2台，2台高压开关设备 所检项目合格	

91	GX-B1310/21-1- 24007	2024. 4. 9	符合标准要求	
92	GX-B1310/21-1- 24008	2024. 4. 9	符合标准要求	

93	GX-B1310/21-1- 24009	2024. 4. 9	符合标准要求	
94	GX-B1310/21-1- 24010	2024. 4. 9	符合标准要求	

95	GX-B1428/21-1-24010	2024. 4. 9	无缺陷迹痕显示	
96	GX-B1310/21-1- 24011	2024. 4. 9	符合标准要求	

97	GX-B1428/21-1-24011	2024. 4. 9	无缺陷迹痕显示	 <p>2024/1/19</p>
98	GX-B1310/21-1-24039	2024. 4. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径缺陷	 <p>2024/03/23</p>



99	GX-B1428/21-1-24039	2024. 4. 9	无缺陷迹痕显示		 <p>2024/03/23</p>
100	GX-B1310/21-1-24040	2024. 4. 9	发现超过 $\Phi 2\text{mm}$ 当量直径缺陷		 <p>2024/03/28</p>



101	GX-B1428/21-1-24040	2024. 4. 9	无缺陷迹痕显示	
102	GX-B1310/21-1-24041	2024. 4. 9	符合标准要求	

103	GX-B1310/21-1-24042	2024. 4. 9	符合标准要求	
104	GX-B1310/21-1-24043	2024. 4. 9	符合标准要求	

105	GX-B1310/21-1-24044	2024. 4. 9	符合标准要求	 <p>2024/03/29</p>
106	GX-B1517/20-1-24013	2024. 4. 10	综合判定：合格	 <p>2024/2/5</p>

107	GX-B1548/20-1-24011	2024. 4. 10	所检项目合格	
108	GX-B1548/20-1-24012	2024. 4. 10	所检项目合格	

109	GX-B1517/20-1-24001	2024. 4. 10	综合判定：合格	 A close-up photograph of a worker wearing a red hard hat and a green jacket, operating a piece of machinery. The worker is looking towards the camera. A yellow timestamp '2024/1/16' is visible in the bottom right corner of the image.
110	GX-B1517/20-1-24002	2024. 4. 10	综合判定：合格	 A photograph of a worker wearing a red hard hat and a black jacket, kneeling on a railway track. The worker is positioned next to a large, reddish-brown structure, possibly a train car or a piece of infrastructure. A yellow timestamp '2024/1/16' is visible in the bottom right corner of the image.



111	GX-B1517/20-1-24003	2024. 4. 10	综合判定：合格	 <p>2024/1/16</p>
112	GX-B1517/20-1-24004	2024. 4. 10	综合判定：合格	 <p>2024/1/16</p>

113	GX-B1517/20-1-24005	2024. 4. 10	综合判定：合格	 <p>A man wearing a red hard hat, safety glasses, and a dark jacket is operating a piece of machinery. He is holding a control lever. The date stamp '2024/1/17' is visible in the bottom right corner of the photo.</p>
114	GX-B1517/20-1-24006	2024. 4. 10	综合判定：合格	 <p>A man wearing a red hard hat and a dark jacket is kneeling on the ground next to a large red electrical cabinet. He appears to be inspecting or working on the cabinet. The date stamp '2024/1/17' is visible in the bottom right corner of the photo.</p>

115	GX-B1517/20-1-24007	2024. 4. 10	综合判定：合格	
116	GX-B1517/20-1-24008	2024. 4. 10	综合判定：合格	

117	GX-B1416/22-1-24002	2024. 4. 10	综合判定：合格	 <p>A worker wearing a blue uniform with reflective stripes, a red hard hat, and safety glasses is kneeling in an industrial environment. He is holding a yellow handheld device and looking at it. The background shows metal structures and a concrete wall. A yellow timestamp '2024/03/29' is visible in the bottom right corner of the photo.</p>
118	GX-B1416/22-1-24003	2024. 4. 10	综合判定：合格	 <p>A worker in a blue uniform with reflective stripes, a red hard hat, and safety glasses is standing in a dark industrial setting. He is looking towards a large piece of machinery. The scene is illuminated by overhead lights. A yellow timestamp '2024/03/29' is visible in the bottom right corner of the photo.</p>

119	GX-B1416/22-1-24004	2024. 4. 10	综合判定：合格	 <p>2024/03/29</p>
120	GX-B1416/22-1-24005	2024. 4. 10	综合判定：合格	 <p>2024/03/29</p>

121	GX-B1310/21-1- 24033	2024. 4. 9	符合标准要求	
122	GX-B1306/23-1-24009	2024. 4. 10	所检项目合格	

123	GX-B1306/23-1-24003	2024. 4. 10	所检项目合格	
124	GX-B1306/23-1-24004	2024. 4. 10	所检项目合格	

125	GX-B1307/20-1-24011	2024. 4. 10	所检项目合格	
126	GX-B1307/20-1-24012	2024. 4. 10	所检项目合格	

127	GX-B1307/20-1-24013	2024. 4. 10	所检项目合格	
-----	---------------------	-------------	--------	---

23045

