










序号	报告编号	发布日期	结论	影像资料
1	GX-B1309/21-P-24003	2024. 6. 1	综合判定：合格。	
2	GX-B1309/21-P-24004	2024. 6. 1	综合判定：合格。	

3	GX-B1500/21-P-24008	2024. 6. 1	综合判定：合格。	 2024/5/14
4	GX-B1500/21-P-24009	2024. 6. 1	综合判定：合格。	 2024/5/14
5	GX-B1500/21-P-24010	2024. 6. 1	综合判定：合格。	 2024/5/14

6	GX-B1500/21-P-24011	2024. 6. 1	综合判定：合格。	
7	GX-B1500/21-P-24012	2024. 6. 1	综合判定：合格。	
8	GX-B1500/21-P-24013	2024. 6. 1	综合判定：合格。	

9	GX-B1500/21-P-24014	2024. 6. 1	<p>启动时间、电动机输入电流合格，流量 75. 5m³ /h。</p>	
10	GX-B1500/21-P-24015	2024. 6. 1	<p>启动时间合格，流量97. 4m³ /h。</p>	
11	GX-B1321/20-P-24220-24221	2024. 6. 3	<p>本次共检电力电缆2条，2条电力电缆所 检项目合格。</p>	 <p>2024.5.14</p>

12	GX-B1534/21-P-24001	2024. 6. 3	综合判定：合格	 <p>2024.4.12</p>
13	GX-B1307/20-P-24012	2024年6月5日	综合判定：合格。	 <p>2024/5/12</p>
14	GX-B1307/20-P-24013	2024年6月5日	综合判定：合格。	 <p>2024/5/12</p>

15	GX-B1307/20-P-24014	2024年6月5日	综合判定：合格。	 A worker wearing a red hard hat and a green t-shirt is operating a large blue industrial machine. The worker is holding a long, light-colored cylindrical object. The machine has a blue frame and a dark interior. The date '2024/5/12' is visible in the bottom right corner of the photo.
16	GX-B1307/20-P-24015	2024年6月5日	综合判定：合格。	 A worker wearing a red hard hat and a green t-shirt is working on a complex industrial machine. The machine has various pipes, valves, and a large cylindrical component. The worker is leaning over the machine, possibly inspecting or adjusting it. The date '2024/5/12' is visible in the bottom right corner of the photo.



