










序号	报告编号	发布日期	结论	影像资料
1	GX-B1328/20-7-24025	2024/6/30	本次共检绝缘手套4只，4只绝缘手套合格。	 A photograph showing a worker in a white lab coat and safety glasses inspecting a set of yellow insulating gloves on a table. The room is a laboratory with white walls and a tiled floor. A date stamp '2024.5.22' is visible in the bottom right corner.
2	GX-B1328/20-7-24026	2024/6/30	本次共检绝缘鞋4只，4只绝缘鞋合格。	 A photograph showing a worker in a white lab coat and safety glasses inspecting a pair of yellow insulating shoes on a table. The room is a laboratory with white walls and a tiled floor. A date stamp '2024.5.22' is visible in the bottom right corner.
3	GX-B1328/20-7-24027	2024/6/30	本次共检验电器2支，2支验电器合格。	 A photograph showing a worker in a white lab coat and safety glasses inspecting a piece of electrical testing equipment. The worker is holding a tool and looking at the equipment. The room is a laboratory with white walls and a tiled floor. A date stamp '2024.5.22' is visible in the bottom right corner.


4	GX-B1328/20-7-24028	2024/6/30	所检项目合格。	
5	GX-B1328/20-7-24029	2024/6/30	本次共检绝缘杆2组， 2组绝缘杆合格。	
6	GX-B1522/20-7-24005	2024/7/1	所检项目合格。	

7	GX-B1522/20-7-24006	2024/7/1	所检项目合格。	
8	GX-B1352/21-7-24036~24041	2024. 7. 2	所检项目合格。	
9	GX-B1352/21-7-24026~24029	2024. 7. 2	所检项目合格。	

10	GX-B1352/21-7-24030~24033	2024. 7. 2	所检项目合格。		
11	GX-B1352/21-7-24034~24035	2024. 7. 2	所检项目合格。		
12	GX-B1495/20-7-24471~24481	2024. 7. 2	本次共检高压开关柜 11台，11台高高压开 关柜所检项目合格		

13	GX-B1495/20-7-24482~24489	2024. 7. 2	本次共检高压开关柜8台，8台高高压开关柜所检项目合格	
14	GX-B1495/20-7-24490~24491	2024. 7. 2	本次共检高压开关柜2台，2台高高压开关柜所检项目合格	
15	GX-B1495/20-7-24492~244502	2024. 7. 2	本次共检高压开关柜11台，11台高高压开关柜所检项目合格	

16	GX-B1495/20-7-24504~244513	2024. 7. 2	本次共检高压开关柜10台，10台高高压开关柜所检项目合格	
17	GX-B1332/21-7-24031~24048	2024. 7. 2	本次共检电容器18台，18台所检项目合格。	
18	GX-B1319/21-7-24001~24005	2024. 7. 2	本次共检高压交流断路器5台，5台所检项目合格。	

19	GX-B1547/20-7-24006~24010	2024. 7. 2	本次共检继电保护装置5台，5台所检项目合格。	
----	---------------------------	------------	------------------------	---