

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|-----------------------------|-----------|--------|--|
| 1 | GX-B1465/22-B-B-24095-24096 | 2024年8月1日 | 所检项目合格 |  A photograph showing two technicians in a laboratory. One technician is wearing a grey uniform with '中检公信' on the back, and the other is in a grey jacket. They are working with equipment on a blue counter. A date stamp '2024.7.1' is visible in the bottom right corner of the image. |
| 2 | GX-B1411/22-B-24093 | 2024.8.2 | 所检项目合格 |  A photograph showing two technicians in a laboratory. One technician is wearing a grey uniform with '中检公信' on the back, and the other is in a light blue shirt. They are working with equipment on a blue counter. A date stamp '2024.7.24' is visible in the bottom right corner of the image. |

| | | | | |
|---|-----------------------------|----------|--------|--|
| 3 | GX-B1412/22-B-24023 | 2024.8.1 | 所检项目合格 |  |
| 4 | GX-B1409/22-B-24047 | 2024.8.1 | 所检项目合格 |  |
| 5 | GX-B1601/22-B-240463~240469 | 2024.8.1 | 所检项目合格 |  |

| | | | | |
|---|-----------------------------|-----------|--------|--|
| 6 | GX-B1374/22-B-240572~240574 | 2024.8.5 | 所检项目合格 |  <p>2024.7.29</p> |
| 7 | GX-B1373/21-B-24297 | 2024年8月2日 | 所检项目合格 |  <p>2024.7.11</p> |
| 8 | GX-B1373/21-B-24296 | 2024年8月2日 | 所检项目合格 |  <p>2024.7.9</p> |

| | | | | |
|----|-----------------------------|-----------|--------|--|
| 9 | GX-B1373/21-B-24345~24354 | 2024年8月2日 | 所检项目合格 |  |
| 10 | GX-B1601/22-B-240397~240410 | 2024.8.5 | 所检项目合格 |  |
| 11 | GX-B1603/22-B-240260~240265 | 2024.8.5 | 所检项目合格 |  |

| | | | | |
|----|-----------------------------|-----------|--------|--|
| 12 | GX-B1603/22-B-240254~240259 | 2024.8.5 | 所检项目合格 |  |
| 13 | GX-B1592/21-B-24080~24083 | 2024.7.29 | 所检项目合格 |  |
| 14 | GX-B1374/22-B-240509~240522 | 2024.7.29 | 所检项目合格 |  |



| | | | | |
|----|---------------------------|-----------|--------|--|
| 15 | GX-B1593/21-B-24357~24361 | 2024.7.29 | 所检项目合格 |  |
| 16 | GX-B1605/23-B-24065 | 2024.7.30 | 所检项目合格 |  |
| 17 | GX-B1606/23-B-24065 | 2024.7.30 | 所检项目合格 |  |

| | | | | |
|----|-----------------------------|-----------|--------|--|
| 18 | GX-B1568/22-B-240318~240322 | 2024.8.5 | 所检项目合格 |  |
| 19 | GX-B1593/21-B-24292~24293 | 2024.7.29 | 所检项目合格 |  |
| 20 | GX-B1592/21-B-24069~24070 | 2024.7.29 | 所检项目合格 |  |

| | | | | |
|----|-----------------------------|-----------|--------|---|
| 21 | GX-B1374/22-B-240449 | 2024.7.29 | 所检项目合格 |  <p>2024.6.30</p> |
| 22 | GX-B1601/22-B-240357~240360 | 2024.8.5 | 所检项目合格 |  <p>2024.6.28</p> |
| 23 | GX-B1603/22-B-240357~240360 | 2024.8.5 | 所检项目合格 |  <p>2024.6.29</p> |

| | | | | |
|----|-----------------------------|-----------|--------|--|
| 24 | GX-B1372/22-B-240506~240514 | 2024.7.31 | 所检项目合格 |  |
| 25 | GX-B1374/22-B-240444~240446 | 2024.7.29 | 所检项目合格 |  |
| 26 | GX-B1601/22-B-240361~240365 | 2024.8.5 | 所检项目合格 |  |

| | | | | |
|----|-----------------------------|-----------|--------|--|
| 27 | GX-B1603/22-B-240222~240223 | 2024.8.5 | 所检项目合格 |  |
| 28 | GX-B1603/22-B-240220~240221 | 2024.8.5 | 所检项目合格 |  |
| 29 | GX-B1593/21-B-24291 | 2024.7.29 | 所检项目合格 |  |



| | | | | |
|----|-----------------------------|-----------|--------|--|
| 30 | GX-B1592/21-B-24068 | 2024.7.29 | 所检项目合格 |  |
| 31 | GX-B1374/22-B-240447~240448 | 2024.7.29 | 所检项目合格 |  |
| 32 | GX-B1542/21-B-24322~24324 | 2024.7.26 | 所检项目合格 |  |

| | | | | |
|----|-----------------------------|-----------|--------|--|
| 33 | GX-B1529/20-B-24318~24321 | 2024.7.25 | 所检项目合格 |  |
| 34 | GX-B1372/22-B-240515~240525 | 2024.7.31 | 所检项目合格 |  |
| 35 | GX-B1373/21-B-24270 | 2024.8.2 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|-----------|--------|--|
| 36 | GX-B1601/22-B-240366 | 2024.8.5 | 所检项目合格 |  |
| 37 | GX-B1592/21-B-24071 | 2024.7.29 | 所检项目合格 |  |
| 38 | GX-B1593/21-B-24294~24296 | 2024.7.29 | 所检项目合格 |  |

| | | | | |
|----|-----------------------------|-----------|--------|--|
| 39 | GX-B1372/22-B-240526 | 2024.7.31 | 所检项目合格 |  |
| 40 | GX-B1540/20-B-241714~241722 | 2024.7.31 | 所检项目合格 |  |
| 41 | GX-B1540/20-B-241702~241713 | 2024.7.31 | 所检项目合格 |  |

| | | | | |
|----|-----------------------------|-----------|--------|--|
| 42 | GX-B1568/22-B-240267~240269 | 2024.8.5 | 所检项目合格 |  |
| 43 | GX-B1528/20-B-24251 | 2024.7.25 | 所检项目合格 |  |
| 44 | GX-B1542/21-B-24316~24321 | 2024.7.25 | 所检项目合格 |  |

| | | | | |
|----|-----------------------------|-----------|--------|--|
| 45 | GX-B1542/21-B-24313~24315 | 2024.7.25 | 所检项目合格 |  |
| 46 | GX-B1568/22-B-240259~240266 | 2024.8.5 | 所检项目合格 |  |
| 47 | GX-B1568/22-B-240270~240275 | 2024.8.5 | 所检项目合格 |  |

| | | | | |
|----|---------------------------|----------|--------|---|
| 48 | GX-B1373/21-B-24298~24299 | 2024.8.2 | 所检项目合格 |  A technician in a light blue uniform with '中检公信' on the back is operating a piece of equipment on a blue cabinet. Another person is partially visible in the background. A date stamp '2024.7.9' is in the bottom right corner. |
| 49 | GX-B1373/21-B-24355~24356 | 2024.8.2 | 所检项目合格 |  Two technicians, one in a grey shirt and one in a light blue uniform with '中检公信' on the back, are working together at a piece of equipment on a blue cabinet. A date stamp '2024.7.20' is in the bottom right corner. |
| 50 | GX-B1373/21-B-24305-24314 | 2024.8.6 | 所检项目合格 |  Two technicians in light blue uniforms with '中检公信' on the back are working at a piece of equipment on a blue cabinet. A date stamp '2024.7.9' is in the bottom right corner. |

| | | | | |
|----|----------------------------|----------|--------|--|
| 51 | GX-B1465/22-B- 24108 | 2024.8.5 | 所检项目合格 |  |
| 52 | GX-B1373/21-B- 24325-24333 | 2024.8.5 | 所检项目合格 |  |
| 53 | GX-B1373/21-B- 24315-24324 | 2024.8.5 | 所检项目合格 |  |

| | | | | |
|----|----------------------------|----------|--------|--|
| 54 | GX-B1466/22-B- 24048-24051 | 2024.8.5 | 所检项目合格 |  |
| 55 | GX-B1466/22-B- 24052-24053 | 2024.8.5 | 所检项目合格 |  |
| 56 | GX-B1373/21-B- 24264-24269 | 2024.8.5 | 所检项目合格 |  |

| | | | | |
|----|----------------------------|----------|--------|---|
| 57 | GX-B1373/21-B- 24258-24263 | 2024.8.2 | 所检项目合格 |  |
| 58 | GX-B1465/22-B-24094 | 2024.8.5 | 所检项目合格 |  |