

序号	报告编号	发布日期	结论	影像资料
12	GX-B1382/21-1-24017	2024. 8. 9	综合判定:合格	 A worker in a blue uniform and red helmet stands next to a complex industrial structure. A bright light source is visible, creating a lens flare effect. A vertical timestamp '2024/03/05' is visible on the left side of the image.
13	GX-B1382/21-1-24018	2024. 8. 9	综合判定:合格	 A worker in a blue uniform and red helmet stands in front of a metal cage. A sign on the cage reads '配重罐笼' (Counterweight Cage). A vertical timestamp '2024/03/05' is visible on the left side of the image.

14	GX-B1308/23-1-24014	2024. 8. 9	综合判定：合格	
15	GX-B1499/23-1-24012	2024. 8. 9	除吨水百米电耗超限外，其余所检项目合格	 2024.07.24

16	GX-B1499/23-1-24013	2024. 8. 9	除吨水百米电耗超限外，其余所检项目合格	 <p>A photograph showing a worker in a blue uniform and red helmet inspecting equipment in a tunnel. The worker is holding a flashlight. The background shows pipes and other equipment in a dimly lit tunnel. A red timestamp '2024.07.24' is visible in the bottom right corner of the image.</p>
17	GX-B1301/23-1-24012	2024/8/12	综合判定：合格	 <p>A photograph showing workers in a factory setting inspecting large green machinery. The workers are wearing red helmets and dark clothing. The machinery is large and green, with a red circular opening. The background shows a factory interior with windows and other equipment. A yellow timestamp '2024/8/9' is visible in the bottom right corner of the image.</p>

18	GX-B1301/23-1-24010	2024/8/12	综合判定：合格。	
19	GX-B1301/23-1-24011	2024/8/12	综合判定：合格。	